

Document: Supporting Photographs and Window Locations

Property: Flat 5, Ace House, 1 Bridge Road, Worthing, West Sussex, BN14 7BU

Proposal: Like-for-like replacement of 2 timber sliding sash windows (Grade II listed building)

Photo 1a - Front elevation (lounge window highlighted)

External view of the front elevation showing **Window 1** serving Flat 5, proposed for like-for-like replacement.

The proposed works will not alter the external appearance.



Photo 1b - Front elevation (lounge window highlighted)

External view of the front elevation showing **Window 1** serving Flat 5, proposed for like-for-like replacement.

The proposed works will not alter the external appearance.



Photo 2a - Side elevation (bedroom window highlighted)

External view of the side elevation showing **Window 2** serving Flat 5, proposed for like-for-like replacement.



Photo 2b - Side elevation (bedroom window highlighted)

External view of the side elevation showing **Window 2** serving Flat 5, proposed for like-for-like replacement.



Photo 2c - Side elevation (bedroom window highlighted)

External view of the side elevation showing **Window 2** serving Flat 5, proposed for like-for-like replacement.



Photo 3 - Window 1 (Front, lounge window) - Internal view

Internal view of **Window 1**, showing existing sash arrangement and glazing pattern to be replicated in the replacement.



**The window frame and glazing bars have been painted black as a result of previous occupation. The proposed replacement will be painted white/off-white to reinstate a finish consistent with the existing windows elsewhere on the listed building.*

Photo 4 - Window 2 (Side, bedroom window) - Internal view

Internal view of **Window 2**, showing glazing bar arrangement and proportions to be matched like-for-like.



**The glazing bars have been painted as a result of previous occupation. The proposed replacement will be painted neatly in white/off-white to reinstate a finish consistent with the existing windows elsewhere on the listed building.*

Photo 5 (Collection of 6 photos) - Window condition detail

6 Photographs showing representative defects (e.g. timber decay, open joints, failed paint finish).





Photo 6 - Aerial view (Google Maps) showing Window 1 and Window 2 (highlighted)

