

WORTHING HIGH SCHOOL, WEST SUSSEX

SUSTAINABLE DRAINAGE STRATEGY

JULY 2026

Ref: 14943/08/HOP/RPT/01

HOP Consulting Limited
HOP House, 41 Church Road
Hove, BN3 2BE
Registered 4402211 England
T: +44 (0)1273 223900

E: ask@hop.uk.com

W: www.hop.uk.com



CONTENTS

1.0	INTRODUCTION	3
2.0	SITE SETTING AND LOCATION	4
3.0	DEVELOPMENT PROPOSALS	5
4.0	SURFACE WATER DRAINAGE STRATEGY	6
5.0	FLOOD RISK	10
6.0	CONCLUSIONS	10

APPENDICES

APPENDIX A	TOPOGRAPHIC & SUB-SURFACE SURVEYS
APPENDIX B	CCTV DRAINAGE SURVEY REPORT
APPENDIX C	ARCHITECTURAL PROPOSALS
APPENDIX D	DRAINAGE LAYOUT DRAWING

Client : Worthing High School
 South Farm Road
 West Sussex
 BN14 7AR

Prepared by	Checked by	Approved by	Status	Revision
Izzy Al-Shimmeri	Andrew Keen	Andrew Keen	S1	P01 31.07.2026

1.0 INTRODUCTION

- 1.1 HOP Consulting Ltd (HOP) has been instructed by Worthing High School to undertake a Sustainable Drainage (SuDS) Strategy report for the modular classrooms on the site of Worthing High School, South Farm Road, Worthing, West Sussex BN14 7AR.
- 1.2 The development proposals are to build two 2-storey modular classrooms connected by a central access ramp, located within the current hard play area at the school.
- 1.3 The site is located within the West Sussex County Council (WSCC) area, which acts as the Lead Local Flood Authority (LLFA). The LLFA have been consulted at the pre-application stage for general guidance for the SuDS approach at the site in line with the National Standards for SuDS (NSfS).
- 1.4 This report also uses guidance from the National Planning Policy Framework (NPPF) and associated Planning Practice Guidance (PPG) for Development and Flood Risk; the CIRIA SuDS Manual (CIRIA 753); data from the Environment Agency (EA) flood maps; and information provided within the local authority's Strategic Flood Risk Assessment (SFRA).
- 1.5 Site investigation work has been undertaken at the site including a topographic and utilities survey and a CCTV drainage survey. Southern water sewer records have also been provided.
- 1.6 Details of the development have been provided by Philips Surveyors LLP and its agents to indicate the extent of the proposals. Reference should be made to the additional details submitted by others for a comprehensive overview of the scheme. This report focuses on the sustainable management of surface water at the site and its content and conclusions reflect the scale of the development.
- 1.7 Information in this report has been received from a number of external parties and HOP does not accept liability for the accuracy of this information. Should there be material change in the development proposals, this report will need to be revised accordingly.




Figure 1.1 Location map

2.0 SITE SETTING AND LOCATION

- 2.1 As can be seen in the location map in Figure 1.1, Worthing High School is approximately 1.6km north-west of the main shopping centre, 590m northwest of Worthing station and approximately 1km north-east of West Worthing station. The school is set in extensive grounds and one large playing field and is bounded on all sides by predominantly residential properties which characterise this part of the town.
- 2.2 Vehicular and pedestrian access is gained off South Farm Road which runs adjacent the eastern boundary of the school.
- 2.3 The school falls slightly from northwest to southeast. The proposed modular classrooms are located within the existing hard play area with buildings to the southern and western sides. Topographic survey data for this area indicates that the ground level ranges from approximately 10.00m Above Ordnance Datum (AOD) to approximately 9.40m AOD.
- 2.4 An aerial image of the location where the replacement classroom is proposed is shown in Figure 2.1 for context, with a photograph of the existing area shown in Figure 2.2. Topographic and sub-surface survey information is included in Appendix A.




Figure 2.1 Aerial image of site




Figure 2.2 Photograph of proposed classroom location

- 2.5 Survey data indicates that the existing site area is served by separate below ground systems of foul and surface water drainage. The current area is impermeable hardstanding and surface water run-off is directed to gullies, from where it is conveyed to the wider surface water drainage network. Data from the CCTV drainage survey (Appendix B) indicates the routes of the below ground drainage and states that the surface water pipework is in poor condition, however, the connectivity is proven for an off-site connection to the public sewer.

- 2.6 As indicated by the British Geological Survey mapping website, the underlying bedrock geology of the site is of the London Clay formation, silt and sand, with superficial deposits of river terrace deposits (Undifferentiated) of sand, silt and clay recorded. Therefore, it is unlikely that infiltration SuDS methods can be successfully utilised for the management of surface water runoff at the site.

3.0 DEVELOPMENT PROPOSALS

- 3.1 The proposals are to construct two 2-storey modular classrooms connected by a central access ramp over the existing impermeable hard play area. Full plans have been submitted by Philips Surveyors LLP and should be referred to for a comprehensive overview of the development proposals. An extract of the site plan is shown in Figure 3.1, with further scheme drawings included in Appendix C.
- 3.2 As can be seen, the new classroom is detached from the surrounding school buildings. The existing site is currently impermeable hardstanding; therefore, the total impermeable area will remain the same on a like-for-like basis. However, SuDS Planters have been introduced to provide betterment by reducing the discharge of surface water runoff into the existing sewer system.
- 3.3 The existing area is currently an impermeable hard play area with an area of approximately 1,550m². The proposed classrooms and ramp have an area of approximately 325m². As the existing area is also impermeable, there is no change in the overall impermeable area on the site.



Figure 3.1 Extract of proposed site plan layout (Philips Surveyors)

4.0 SURFACE WATER DRAINAGE STRATEGY

Existing

- 4.1 The surface water run-off from the existing hardstanding discharges directly into gullies and is directed to the wider network discharging into a combined sewer south of the site. Existing runoff rates from the 325m² contributing catchment are considered impractical to model accurately using industry standard hydraulic modelling software and therefore existing runoff rates have been indicated for a range of storm intensities, as indicated in Table 4.1

Table 4.1 Existing runoff rates for range of storm intensities prior to mitigation

Rainfall intensity (mm/hour)	10	30	50	75	100
Runoff rate (litres/second)	0.90	2.71	4.51	6.77	9.03

- 4.2 No existing SuDS features (e.g. attenuation tanks or flow limiting devices) have been identified as serving the surface water drainage system at the school.

Proposed

- 4.3 The scale of the proposed new classrooms and central access ramp development, together with the like-for-like impermeable areas due to the scheme, has been considered in the SuDS approach to manage surface water runoff from the new modular buildings. The primary strategy is to install SuDS Planters below rainwater downpipes to intercept and slow runoff as a secondary measure before discharging to the existing piped drainage network. Additionally, channel drains will be installed to capture surface water runoff at ground level.
- 4.4 The surface water system will ultimately discharge to the public sewer via the piped network, which will be intercepted by the SuDS planters. There will be no increase in flows to the sewer due to the impermeable area remaining the same.
- 4.5 There are several examples of SuDS Planters available as proprietary products that would suit the Worthing High School application. For referencing purposes, the Meristem Design systems are considered to be a suitable option.
- 4.6 These systems operate by intercepting runoff directly from rainwater downpipes and directing the flow into the raised planter unit. The water then infiltrates through the soil and growing material, as well as into the storage medium located at the base of the unit, before discharging via an outlet to the downstream drainage network. Figure 4.1 provides an illustration of how the SuDS Planter system operates. Figure 4.2 shows an image of a SuDS Planter installation.




Figure 4.1 SuDS Planter diagrammatic section (Meristem Design 2026)



Figure 4.2 SuDS Planter installation (Meristem Design 2026)

- 4.7 The system is available in modular units of varying sizes, with the largest planter unit being able to provide 800 litres of rainwater storage. The arrangement of these planters adjacent the new modular classroom, along with the additional new drainage infrastructure required to serve the scheme, are shown in drainage layout drawings included in Appendix E.

4.8 This strategy has been developed from consideration of the site constraints and the suitability of available SuDS options. Pre-application discussions with the LLFA were favourable to the acceptance of such an approach, as it was acknowledged that there was to be no increase in the impermeable area of the site post-development.

4.9 With regard to the Standards as set out in the NSfS, the following sections provide a brief description of how these are addressed at the site.

Standard 1: runoff destinations

4.10 As demonstrated in Section 2.0, infiltration opportunities are restricted by the clayey ground conditions and cannot be practically pursued. The existing arrangement is for surface water to discharge to the below ground drainage network and this strategy is to be retained for the developed site for the runoff destination.

Standard 2: management of everyday rainfall (interception)

4.11 The introduction of SuDS Planters provides interception to the first 5mm of rainfall with flows prevented from entering the downstream piped network by diverting runoff into the soil and attenuation medium.

Standard 3: management of extreme rainfall and flooding

4.12 Flow rates to the downstream piped network are greatly reduced through the use of SuDS Planters, as these act as above ground attenuation features that capture and slow the flow prior to discharge to the existing system.

4.13 With attenuation storage potential of 800 litres available to be accommodated in one unit, it can be seen that this provides significant betterment over the existing drainage arrangement where runoff from the impermeable surfacing at the site is discharged directly into the below ground system with no SuDS features present.

4.14 The Meristem Design SuDS Planters can be designed to bespoke sizes with flow restricting orifice plates on the outlet pipes. This means that the rate of flow from the roof runoff can be slowed down and limited for a specific range of storm events resulting in a reduction of the hydraulic load on the downstream piped drainage network.

4.15 Detailed hydraulic calculations are outside the scope of this strategy report, however, it is considered that a 30% reduction of runoff rates could be achieved for up to a storm intensity of 50mm/hour, with more intense storms subject to a 10% reduction up to the 1 in 100-year event. Table 4.2 indicates the reduced runoff rate that could potentially be introduced through SuDS Planter mitigation.

Table 4.2 Reduced runoff rates for range of storm intensities after SuDS Planter mitigation

Rainfall intensity (mm/hour)	10	30	50	75	100
Runoff rate (litres/second)	0.60	1.81	3.01	6.09	8.13
Reduction from existing (litres/second)	-0.3	-0.90	-1.50	-0.68	-0.90

- 4.16 This is considered to be a betterment over the existing situation and also over the general assumption that replacing like-for-like impermeable catchment areas with new development does not have an adverse effect on the overall drainage arrangement. It can be seen that the introduction of SuDS Planters will have a beneficial impact on the school site and downstream public sewer network in terms of drainage capacity, despite the small-scale nature of the works.

Standard 4: water quality

- 4.17 Runoff from small, non-industrial roofs and pedestrian hardstanding areas is considered in the SuDS Manual to be at low risk of containing potential contaminants and minimal intervention is needed to improve the quality of discharge to downstream receptors. As with Standard 3, the introduction of SuDS Planters provides the opportunity to significantly improve the runoff treatment through filtration to a better standard than via a direct connection to the below ground drainage.

Standard 5: amenity

- 4.18 As shown in the photograph in Figure 2.2, the development of the existing courtyard area presents an opportunity to add educational and recreational value to the external spaces. The SuDS Planters are particularly suited to a school environment, with many products available featuring interactive elements and information boards that explain the benefits of SuDS and the importance of rainwater as a resource. These add to the amenity of the courtyard space and the new teaching accommodation.

Standard 6: biodiversity

- 4.19 It can also be seen how biodiversity is enhanced through the additional planting and habitat created from the proposed SuDS features.

Standard 7: design of drainage for construction, operation, maintenance, decommissioning and structural integrity

- 4.20 Proprietary planter units are installed and maintained to the manufacturer's guidance, which will be made available to the school facilities management team. The anticipated routine inspections will focus on the unobstructed conveyance of runoff through the system with the removal of any blockages, siltation, litter and other debris conducted monthly and after periods of heavy rainfall.
- 4.21 The plants and growing medium should be inspected as required to ensure plant health. This is envisaged to be incorporated into the existing landscape management schedule and maintenance programme, with the school responsible for the maintenance and management of the SuDS features for their operational lifetime.
- 4.22 With the planters being stand-alone above ground features, it is considered that the installation and decommissioning of these units can be achieved independently of the wider construction requirements of the classroom building.

5.0 FLOOD RISK

- 5.1 A Flood Risk Assessment is not required for the development as the scale of the project is less than one hectare and is located wholly within Flood Zone 1, as indicated by the EA online flood maps for planning. Additional sources of flood risk have been reviewed and the risk of flooding from all sources, including surface water flood risk, is considered to be low.

6.0 CONCLUSIONS

- 6.1 This Sustainable Drainage Strategy has been prepared in support of the proposed modular classrooms and ramp development at Worthing High School, West Sussex. The proposals comprise two 2-storey modular classrooms with a central access ramp over an existing impermeable play area.
- 6.2 Topographic and drainage surveys have been undertaken to inform the drainage strategy. The investigation findings confirm that infiltration opportunities at the site are limited and therefore, infiltration-based SuDS techniques are not considered feasible for this development.
- 6.3 The proposed development represents a like-for-like replacement of existing impermeable areas. Surface water runoff from the proposed classroom roof will continue to discharge to the existing drainage network. However, the proposed strategy introduces SuDS Planters to provide interception, attenuation and treatment of runoff prior to discharge.
- 6.4 SuDS measures proposed for the scheme are considered appropriate and proportionate to the scale and nature of the development and provide an overall betterment compared with the existing drainage arrangement.
- 6.5 The strategy aims to reduce and slow runoff entering the downstream drainage network through interception and attenuation. The planters are considered to improve surface water runoff and contribute to enhancing biodiversity, amenity and educational benefits within the school environment.
- 6.6 The SuDS strategy detailed within this report is considered to be compliant with the principles of the NSfS, the NPPF and CIRIA SuDS guidance. The site is located wholly within Flood Zone 1 and is considered to be at low risk of flooding from rivers and the sea, surface water or other sources. The development is therefore considered acceptable in flood risk and drainage terms and this report is considered to be suitable to support the proposed modular classrooms development at Worthing High School.



APPENDIX A – TOPOGRAPHIC & SUB-SURFACE SURVEY



LAND, BUILDING, PAS128 - UTILITY DETECTION, CCTV DRAINAGE & UAV SURVEYS.
Established 1975. Member of The Survey Association.

OPEN SPACE, LEIGH SUTTON ROAD, UPPER INTERFIELDS, MALVERN, WR14 1UT
TEL: 01885 833173 email: london@laser-surveys.com
OLD DARRY, STUBBERS FARM, MOUNTNESS ROAD, BLACKMORE, OX4 0XK
TEL: 01277 821555 email: london@laser-surveys.com
Copyright © Laser Surveys Limited, 2025. All Rights Reserved.

DATUM NOTES

CO-ORDINATES USED ARE BASED ON ORDNANCE SURVEY NATIONAL GRID, OBTAINED USING THE ACTIVE GPS NETWORK AND ADJUSTED TO A LOCAL GRID WITH A SCALE FACTOR OF 1.0000.

LEVELS ARE RELATED TO - ORDNANCE SURVEY ACTIVE GPS NETWORK.

ABBREVIATIONS (where applicable)

(A) Assumed/Approx.	U/R Iron Railings	S/C Surcharged
A/C Assumed Connection	JB Junction Box	SD Site Depth
A/R Assumed Route	JN Junction	SK Sockway
A Arch Height	KD Kerb Outlet	SL Silt Level
AC Air-Con Unit	LB Litter Bin	SP Spring Height
AG Above Ground	LP Lamp Post	SPT Septic Tank
AV Air Valve Cover	LU Line Up	ST Silt Trap
B Beam-Ht	MC Material Change	SV Stop Valve Cover
BL Backdrop Invert Level	MG Multi Girth Tree	SVC Security Video Camera
BK Black	MH Manhole Cover	SW Storm Water
BS Bulbed	MK Moulder	T/CB Telephone Call Box
BS Bus Stop	NDP No Depth Possible	THL Threshold Level
BSJ Beam Sides Up	NPV No Pipes Visible	TL Traffic Light
BT Broken Telecom Cover	NDPV No Other Pipes Visible	TK Tank
C Ceiling Height	NWV No Valve Visible	TP Telegraph Pole
C/B Close Boarded	OH Overhead	TVWS Ben Number in CCTV Report
CF Cofferdam	-C Overhead Cables	UG Underground
CL Cover Level	-E Overhead Electric	UTC Unable to Locate
CLK Chantlink	-T Overhead Telecoms	-A No Access
CP Catch Pit	PE Pipe	-BM -Bout Mosaic
CO Column	PB Post Box	-DRP Drop Pipe
CON Concrete	PD Pit Depth	-F Flow/Water Level
CP Catch Pit	PE Pipe	-BM -Bout Mosaic
OD Column	PB Post Box	-DRP Drop Pipe
OPS Concrete Paving Slabs	PL Pit Level	-RT -Roots
CSJ Gelling Slopes Up	PM Parking Meter	-S/C -Surcharged
CATV Cable Television Cover	PP Pump Pit	UTF Unable to Trace Further
CTV Cable Television Cover	P/R Post and Rail	UTL Unable to Locate
CW Combined Water	PSC Pipe Size Change	UTR Unable to Raise
DC Drainage Channel	PT Post	UTT Unable to Trace
D Depth of Utility	P/W Post and Wire	VP Vent Pipe
D Door Ht (Building)	RE Rooding Eye	WL Water Level
DP Drain Pipe	RET Retaining	WM Water Meter Cover
EP Electricity Pole	RS Road Sign	WO Wash Out Cover
ER Earthing Rod	RSJ Road Sign Illuminated	WPR Wooden Post & Rail
FC False Ceiling Ht	RSJ Road Sign Illuminated	
FB Flower Bed	S Sill Height	
FE Fence	SA Survey Abandoned	
FH Fire Hydrant Cover	-BE -Block at Bend	
FL Floor Level	-CXI -Intruding Connection	
FP Flag Pole	-DA -Debris Attached	
FW Four-Water	-DS -Debris Settled	
GP Gate Post	-JD -Joint Displaced	
GV Gate Valve Cover	-LT -Loss of Traction	
GU Gully	-OB -Obstruction	
H Head Height	-OL -Operating Limit	
HLE High Level Invert	-RT -Roots	
HT Height	-SDP -Small Diameter Pipe	
IC Inspection Cover	-ST -Camera Stuck	
I Invert Level	-UW -Under Water	
I/INT Interceptor	SC Pipe Size Change	

NOTES

- Drainage pipe sizes (where shown) have been gauged from the surface for safety reasons and should be regarded as approximate only.
- Drainage pipe sizes are 1000 unless stated otherwise along the length.
- Tree species (where shown) should be treated with caution and expert identification is advised.
- Although this is a digital survey the accuracy and amount of detail shown is only commensurate with the graphical scale of mapping as specified. Care should be exercised when working to larger scales.
- Visible features in the vicinity of the boundaries as shown above, may not represent the extent of legally conveyed ownership.
- Whilst every effort has been made to achieve accuracy on this plan, CRUCIAL clearance dimensions, levels and invert levels should be checked prior to design and construction.
- Kerb levels have been taken in the bottom of the channel.

SHEET LAYOUT

(NOT TO SCALE)

1

2

WORTHING HIGH SCHOOL,
BN14 7AR

TOPOGRAPHICAL & UTILITY DETECTION SURVEY

CLIENT: PHILLIPS SURVEYORS
SURVEY DATE: MARCH 2026
DRAWN BY: A/R / L/S
CHECKED BY: C/W

SHEET NUMBER N 3091/1
DRAWING TITLE TOPO / UTILITIES
SCALE 1 : 100 (@A1)

SEE ALSO DRAWING NOS.

SHEET 1 of 2
JOB NUMBER N 3091

REVISION INFORMATION

NO. DATE NOTES
1 25/3/26 Amendments amended (RM - Root Mass)
2 16/06/26 Between previous sited drainage runs and extend survey southwards through car park (GR)

103950.000mN

103950.000mN

103925.000mN

103925.000mN

Underground Utility Notes:

- Although Laser Surveys Limited have followed the site methodologies in accordance to PAS128:2022 (survey type D), the desktop utility records search (survey type D) has not been carried as part of this contract, as instructed by our client.
- No utility mapping survey can be considered a 100% accurate depiction of the sub-surface environment, the use of these drawings does not remove the requirement for the use of safe digging techniques, in line with the requirements of HSG47 and CDM regulations.
- The data presented in this drawing has been collected using a combination of the following: visual survey, electromagnetic location, and ground penetrating radar (GPR). These techniques have been deployed in accordance with PAS128:2022 Underground utility detection, verification and location - Specification. (As instructed by our client no desktop utility search has been conducted)
- Unless otherwise stated, all utilities shown on this plan have been surveyed using approved detectors and the connections between inspection chambers, if unable to be detected, are assumed to be direct unless there are indications to the contrary.
- The detection confidence (quality level) for each utility segment is depicted within the object line style (e.g. -B2).
- The utility routes depicted may reflect the routes of multiple cables or pipes. It is not always possible to differentiate between buried construction features, utilities and other subsurface features therefore some features shown may not be utility related. Due to the limitations of techniques employed all utility identifications should be treated with caution and verified prior to design/build works.
- The material and ground conditions surrounding and particularly above buried utilities can lead to inferior data resolution when using ground penetrating radar, e.g. reinforced concrete, standing ground water, saturated ground, soil types, and changes in feature material.
- Small gullies and downpipes that go straight into the ground can not always be traced due to restrictive access.
- Note that not all buried utilities can be detected and mapped due to (but not limited by) their depth, location, material, geology and proximity to other utilities. Even an appropriate and professionally executed survey may not be able to achieve a 100% detection rate.

Combined Heat and Power	Heating Pipes
Drainage Combined	Oil/Fuel Pipeline
Drainage Foul	Telecoms - BT
Drainage Storm	Telecoms - Fibre Optic
Electric - High Voltage	Telecoms - General
Electric - Low Voltage	Traffic Signals
Electric - Street Lighting	Unidentified Cable
Electric - Unidentified	Unidentified Pipe
Empty Duct	Virgin Media
Gas	Water
GPR Linear Feature*	Survey Area Boundary
	(-xx is detection confidence on drawing)
	No GPR Survey Undertaken (Overgrown/Obstructions)
	Limited GPR Survey Undertaken (Ground Conditions/Obstructions)

PAS 128:2022 Quality level of Survey Outputs; (referred to as 'Table 1')				
Survey Type	Quality level (Precision/level of detail)	Post-processing (GPR data post-processed)	Location accuracy	Supporting Data
D Desktop Utility Records Search	QL-D	-	Undefined	Undefined
C Site Reconnaissance	QL-C	-	Undefined	Undefined
B Detection	QL-B4	No	Undefined	Undefined
	QL-B3	No	±500mm	Horizontal location only of the Utility detected by one of the geophysical techniques used.
	QL-B3P	Yes	Horizontal and Vertical location of the Utility detected by one of the geophysical techniques used.	
	QL-B2	No	±250mm or ±125mm of detected depth whichever is greater	Horizontal and Vertical location of the Utility detected by one of the geophysical techniques used.
	QL-B2P	Yes	±150mm or ±125mm of detected depth whichever is greater	Horizontal and Vertical location of the Utility detected by multiple geophysical techniques used.
	QL-B1	No	±150mm or ±125mm of detected depth whichever is greater	Horizontal and Vertical location of the top and/or bottom of the utility. Additional attribution is recorded as specified in 9.2.5.
	QL-B1P	Yes	±150mm or ±125mm of detected depth whichever is greater	Horizontal and Vertical location of the top and/or bottom of the utility. Additional attribution is recorded as specified in 9.2.5.
A Verification	QL-A	-	±50mm	±25mm



103875.000mN

103850.000mN

514175.000mE

514175.000mE

514200.000mE

514200.000mE

514225.000mE

514225.000mE



LAND, BUILDING, PAS128 - UTILITY DETECTION, CCTV DRAINAGE & UAV SURVEYS.
Established 1975. Member of The Survey Association.
OPEN SPACE, LEIGH SINTON ROAD, LIPPER INTERFIELDS, MALVERN, WR14 1UT
TEL: 01885 833173 email: enquiries@laser-surveys.com
OLD DARY, STUBBERS FARM, MOUNTNESSING ROAD, BLACKMORE, OX4 0NX
TEL: 01277 821555 email: london@laser-surveys.com
Copyright © Laser Surveys Limited, 2025. All Rights Reserved.

DATUM NOTES

CO-ORDINATES USED ARE BASED ON ORDNANCE SURVEY NATIONAL GRID, OBTAINED USING THE ACTIVE GPS NETWORK AND ADJUSTED TO A LOCAL GRID WITH A SCALE FACTOR OF 1.0000.

LEVELS ARE RELATED TO - ORDNANCE SURVEY ACTIVE GPS NETWORK.

ABBREVIATIONS (where applicable)

(A)	Assumed/Approx.	I/R	Iron Railings	S/C	Surcharged
A/C	Assumed Connection	JB	Junction Box	SD	Set Depth
A/R	Assumed Route	JN	Junction	SK	Skewway
A	Arch Height	KD	Kerb Outlet	SL	Site Level
AC	Air-Con Unit	LB	Liter Bin	SP	Spring Height
AG	Above Ground	LP	Lamp Post	SPT	Septic Tank
AV	Air Valve Cover	LU	Line Up	ST	Site Trap
B	Beam Hit	MC	Material Change	SV	Stop Valve Cover
BL	Backdrop Invert Level	MG	Multi Girth Tree	SVC	Security Video Camera
BK	Black	MH	Manhole Cover	SW	Storm Water
BL	Bulldozed	MK	Mast	TGB	Telephone Call Box
BS	Bus Stop	NDP	No Depth Possible	THL	Threshold Level
BSU	Beam Spikes Up	NPV	No Pipes Visible	TL	Traffic Light
BT	British Telecom Cover	NDPV	No Other Pipes Visible	TL	Tank
C	Ceiling Height	NWV	No Valve Visible	TP	Telegraph Pole
C/B	Close Boarded	OH	Overhead	TVix	Item Number in CCTV Report
C/F	Coatfast	-C	Overhead Cables	US	Underground
CL	Cover Level	-E-	Overhead Electric	UTC-	Unable to Camera
CLK	Chalkmark	-T-	Overhead Telecoms	-A	No Access
CN	Connection	PWJ	Paving	-D	-Ditch
CO	Column	PB	Post Box	-DRP	-Drop Pipe
Conc	Concrete	PD	Pit Depth	-F	-Flow/Water Level
CP	Catch Pit	PE	Pipe	-BM	-Burst Mass
CPS	Concrete Paving Slabs	PL	Pit Level	-RT	-Roots
CSU	Ceiling Slopes Up	PM	Parking Meter	UTT	Unable to Trace Further
CATV	Cable Television Cover	P/R	Post and Rail	UTL	Unable to Locate
CTV	Cable Television Cover	P/R	Post and Rail	UTL	Unable to Locate
CW	Combined Water	PSC	Pipe Size Change	UTR	Unable to Raise
DC	Drainage Channel	PT	Post	UTT	Unable to Trace
D	Depth of Utility	P/W	Post and Wire	VP	Vent Pipe
D	Door Ht (Building)	RE	Rodding Eye	WL	Water Level
DP	Drain Pipe	RET	Retaining	WM	Water Meter Cover
EP	Electricity Pole	RS	Road Sign	WO	Wash Out Cover
ER	Earthing Rod	RSI	Road Sign Illuminated	WPR	Wooden Post & Rail
FC	False Ceiling Ht	RSI	Road Sign Illuminated	WPR	Wooden Post & Rail
FB	Flower Bed	S	Sill Height		
FE	Fence	SA-	Survey Abandoned		
FH	Fire Hydrant Cover	-BE	-Block at Bend		
FL	Floor Level	-CX	-Including Connection		
FP	Flag Pole	-DA	-Detritus Attached		
FW	Four Water	-DS	-Detritus Settled		
GP	Gate Post	-JD	-Joint Displaced		
GV	Gate Valve Cover	-LT	-Loss of Traction		
GV	Gully	-OB	-Obstruction		
H	Head Height	-OL	-Operating Limit		
HL	High Level Invert	-RT	-Roots		
HT	Height	-SDP	-Small Diameter Pipe		
IC	Inspection Cover	-ST	-Camera Stuck		
I	Invert Level	-UW	-Under Water		
I/NIT	Interceptor	SC	Pipe Size Change		

NOTES

- Drainage pipe sizes (where shown) have been gauged from the surface for safety reasons and should be regarded as approximate only.
- Drainage pipe sizes are 1000 unless stated otherwise along the length.
- Tree species (where shown) should be treated with caution and expert identification is advised.
- Although this is a digital survey the accuracy and amount of detail shown is only commensurate with the graphical scale of mapping as specified. Care should be exercised when working to larger scales.
- Visible features in the vicinity of the boundaries as shown above, may not represent the extent of legally conveyed ownership.
- Whilst every effort has been made to achieve accuracy on this plan, CRUCIAL clearance dimensions, levels and invert levels should be checked prior to design and construction.
- Kerb levels have been taken in the bottom of the channel.

SHEET LAYOUT

(NOT TO SCALE)

1

2

WORTHING HIGH
SCHOOL,
BN14 7AR

TOPOGRAPHICAL & UTILITY DETECTION
SURVEY

CLIENT: PHILLIPS SURVEYORS
SURVEY DATE: MARCH 2025
DRAWN BY: A/R / L/S
CHECKED BY: C/W

SHEET NUMBER N 3091/2
Revision 2

DRAWING TITLE TOPO / DRAINAGE
SCALE 1 : 100 (@A1)

SEE ALSO DRAWING NOS.

SHEET 2 of 2
JOB NUMBER N 3091

REVISION INFORMATION

NO. DATE NOTES
1 25/02/26 Amendments amended (RM - Root Mass)
2 16/06/26 Amend previous tiled drainage runs and extend survey southwards through car park (GR)

Underground Utility Notes;

- Although Laser Surveys Limited have followed the site methodologies in accordance to PAS128:2022 (survey type B), the desktop utility records search (survey type D) has not been carried out as part of this contract, as instructed by our client.
- No utility mapping survey can be considered a 100% accurate depiction of the sub-surface environment, the use of these drawings does not remove the requirement for the use of safe digging techniques, in line with the requirements of HSG47 and CDM regulations.
- The data presented in this drawing has been collected using a combination of the following: visual survey, electromagnetic location, and ground penetrating radar (GPR). These techniques have been deployed in accordance with PAS128:2022. Underground utility detection, verification and location - Specification. (As instructed by our client no desktop utility search has been conducted)
- Unless otherwise stated, all utilities shown on this plan have been surveyed using approved detectors and the connections between inspection chambers, if unable to be detected, are assumed to be direct unless there are indications to the contrary.
- The detection confidence (quality level) for each utility segment is depicted within the object line style (e.g. -B2).
- The utility routes depicted may reflect the routes of multiple cables or pipes. It is not always possible to differentiate between buried construction features, utilities and other subsurface features therefore some features shown may not be utility related. Due to the limitations of techniques employed all utility identifications should be treated with caution and verified prior to design/build work.
- The material and ground conditions surrounding and particularly above buried utilities can lead to inferior data resolution when using ground penetrating radar, e.g. reinforced concrete, standing ground water, saturated ground, soil types, and changes in feature material.
- Small gullies and downpipes that go straight into the ground can not always be traced due to restrictive access.
- Note that not all buried utilities can be detected and mapped due to but not limited by their depth, location, material, geology and proximity to other utilities. Even an appropriate and professionally executed survey may not be able to achieve a 100% detection rate.

Combined Heat and Power	Heating Pipes
Drainage Combined	DI/Tall Pipelines
Drainage Foul	Telecoms - BT
Drainage Storm	Telecoms - Fibre Optic
Drainage Unidentified	Telecoms - General
Electric - High Voltage	Traffic Signals
Electric - Low Voltage	Unidentified Cable
Electric - Street Lighting	Unidentified Pipe
Electric - Unidentified	Unidentified Service
Empty Duct	Virgin Media
Gas	Water
GPR Error Feature*	Survey Area Boundary

* All GPR data is post processed unless specified otherwise.

No GPR Survey Undertaken (Overgrown/Ground Conditions/Obstructions)

Limited GPR Survey Undertaken (Ground Conditions/Obstructions)

PAS 128:2022 Quality level of Survey Outputs; (referred to as 'Table 1')				
Survey Type	Quality level (Practitioner to determine post-survey)	Location accuracy		Supporting Data
		Horizontal	Vertical	
D Desktop Utility Records Search	QL-D	-	Undefined	-
C Site Reconnaissance	QL-C	-	Undefined	A Segment of Utility whose location is demonstrated by visual reference to street furniture, topographical features or evidence of previous street works (reinstatement work).
B Detection	QL-B4	No	Undefined	A Utility Segment which is suspected to exist but has not been detected and is therefore shown as an assumed route.
	QL-B3	No	±500mm	Horizontal location only of the Utility detected by one of the geophysical techniques used.
	QL-B3P	Yes	Undefined (No reliable depth measurement possible)	
	QL-B2	No	±250mm or ±40% of detected depth whichever is greater	Horizontal and Vertical location of the Utility detected by one of the geophysical techniques used.
	QL-B2P	Yes	±150mm or ±15% of detected depth whichever is greater	
	QL-B1	No	±150mm or ±15% of detected depth whichever is greater	Horizontal and Vertical location of the Utility detected by multiple geophysical techniques used.
A Verification	QL-B1P	Yes	±150mm or ±15% of detected depth whichever is greater	
	QL-A	-	±50mm	Horizontal and vertical location of the top and/or bottom of the utility. Additional attribution is recorded as specified in 9.2.5.

APPENDIX B – CCTV DRAINAGE SURVEY REPORT



laser surveys
land, building and underground services

Laser Surveys Limited

Leigh Sinton Road, Malvern

Tel. 01886 833 173

worcester@lasersurveys.com

Project Information

Project Name	Project Number	Project Date
N3091-Worthing High School	N3091	20/03/2026

Client

Company: Phillips Surveyors
Contact: Will Court
Department: The Old Coach House
Street: 78 Lower Street
Town or City: Pulborough
Post Code: RH20 2AA
Phone: 07917224872
Email: will@phillips-surveyors.co.uk

Site

Department: Worthing High School
Street: S Farm Road
Town or City: Worthing
Post Code: BN14 7AR

Contractor

Company: Laser Surveys Limited
Department: Open Space
Street: Leigh Sinton Road
Town or City: Malvern
County: Worcestershire
Post Code: WR14 1UT
Phone: 01886 833 173
Email: worcester@lasersurveys.com



laser surveys
land, building and underground services

Scoring Summary

Project Name
N3091-Worthing High School

Project Number
N3091

Project Date
20/03/2026

Structural Defects

Grade 3: Best practice suggests consideration should be given to repairs in the medium term.

Grade 4: Best practice suggests consideration should be given to repairs to avoid a potential collapse.

Grade 5: Best practice suggests that this pipe is at risk of collapse at any time. Urgent consideration should be given to repairs to avoid total failure.

Section	PLR	Grade	Description
4	SW01 XX	4	Broken pipe from 12 o'clock to 4 o'clock

Service / Operational Condition

Grade 3: Best practice suggests consideration should be given to maintenance activities in the medium term.

Grade 4: Best practice suggests consideration should be given to maintenance activity to avoid potential blockages.

Grade 5: Best practice suggests that this pipe is at a high risk of backing up or causing flooding.

Section	PLR	Grade	Description
3	UTFX	5	Roots, mass, 75% cross-sectional area loss
4	SW01 XX	3	Multiple defects
28	SW02 XX	3	Joint displaced, medium
29	SW03X	3	Joint displaced, medium
39	SW06 XX	3	Multiple defects
40	GullyX	5	Roots, mass, 35% cross-sectional area loss

Abandoned Surveys

Section	PLR	Description
1	UTFX	Survey abandoned
2	UTFX	Survey abandoned
3	UTFX	Survey abandoned
4	SW01 XX	Survey abandoned
31	UTFX	Survey abandoned
34	GullyX	Survey abandoned
40	GullyX	Survey abandoned

Information

These scoring summaries are based on the SRM grading from the WRc.



Defect Grade Description (Section)

Project Name	Project Number	Project Date
N3091-Worthing High School	N3091	20/03/2026

1:	Brick: No structural defects. Other: No structural defects. Acceptable structural condition.
2:	Brick: Circumferential cracking; single longitudinal crack; surface mortar loss (depth missing < 15mm); surface damage - slight spalling (breaking away of small fragments from the surface); surface damage - slight wear (increased roughness). Other: Circumferential crack; moderate joint defects (i.e. medium open joint or medium displaced joint); surface damage - slight spalling (breaking away of small fragments from the surface) or slight wear (increased roughness). Minimal collapse likelihood in the short term but potential for further deterioration.
3:	Brick: Medium mortar loss (depth missing 15-50mm) without other defects; more than one longitudinal crack (at a single location); multiple cracking; single bricks displaced; deformation < 5%; no fracture and only moderate mortar loss; surface damage - medium spalling (large areas of chipped brick); surface damage - medium wear (large area of brick surface is missing). Other: Fracture with no deformation or deformation < 5%; longitudinal cracking or multiple cracking; minor loss of level; severe joint defects (i.e. large open joint or large displaced joint); surface damage - partial area of pipe surface is missing or worn. Collapse unlikely in the near future but further deterioration likely.
4:	Brick: Total mortar loss (depth missing > 50mm) with deformation > 10%; deformation up to 10% and fractured; displaced or hanging brickwork; small number of missing bricks; dropped invert (drop > 20mm); moderate loss of level; surface damage - large spalling (entire surface of brick is missing); surface damage - large wear (entire surface of brick is missing). Other: Broken; deformation up to 10% and broken; fracture with deformation 5-10%; multiple fractures; serious loss of level; serious joint defects with voids or soil visible (open joint with > 50mm soil or void visible or joint displacement > 25% of diameter); surface damage - entire area of pipe surface is missing or severely worn. Collapse likely in the foreseeable future.
5:	Brick: Already collapsed; missing Invert; deformation > 10% and fractured; displaced or hanging brickwork and deformation < 10%; extensive areas of missing brickwork. Other: Already collapsed; deformation > 10% and broken; extensive areas of pipe fabric missing; fractures with deformation > 10% Collapsed or collapse imminent.



Section Inspection

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
1	1	20/03/26	8:48	Not Specified	No Rain Or Snow	No	UTFX
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Ash		Van 3		Camera 3	Not Specified	Not Specified	Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: UTF
Road:	Inspected Length: 13.30 m	Upstream Pipe Depth:
Location:	Total Length: 13.30 m	Downstream Node: SW01 A
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Start of N3091-Vid001 @ 00 00 00		
Recommendations:		

Scale:	1:116	Position [m]	Code	Observation	Photo	Grade			
Depth: m SW01 A									
	0.00	MH		Start node, manhole, reference: SW01 A					
	0.00	WL		Water level, 5% of the vertical dimension					
	0.25	JDL		Joint displaced, large		1 / 4			
	0.50	LL		Line deviates left					
	0.70	S01	DES	Settled deposits, fine, 10% cross-sectional area loss, start					
	1.30		JN	Junction at 9 o'clock, 100mm dia					
	1.70		RF	Roots, fine		2			
	3.50	F01	DES	Settled deposits, fine, 10% cross-sectional area loss, finish		3			
	6.60		DES	Settled deposits, fine, 5% cross-sectional area loss		3			
	13.10		SA	Survey abandoned: Deposits Attached					
	13.30		DEEJ	Attached deposits, encrustation at joint from 12 o'clock to 12 o'clock, 20% cross-sectional area loss	1	3			
	13.30			End of pipe					
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	2.0	0.2	2.0	1.0	5	7.0	1.2	16.0	4.0

Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
1	Upstream	UTFX		N3091



1, 00:01:03, 13.30 m

Attached deposits, encrustation at joint from 12 o'clock to 12 o'clock, 20% cross-sectional area loss



Section Inspection

Item No. 2	Insp. No. 1	Date 20/03/26	Time 8:48	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR UTFX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: UTF
Road:	Inspected Length: 13.30 m	Upstream Pipe Depth:
Location:	Total Length: 13.30 m	Downstream Node: SW01 B
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 02 00		
Recommendations:		

Scale:	1:116	Position [m]	Code	Observation	Photo	Grade			
Depth: m SW01 B									
	0.00	MH	Start node, manhole, reference: SW01 B						
	0.00	WL	Water level, 5% of the vertical dimension						
	0.50	LL	Line deviates left						
	5.20	JN	Junction at 3 o'clock, 100mm dia						
	12.80	DES	Settled deposits, fine, 50% cross-sectional area loss		1, 2	4			
	13.30	SA	Survey abandoned: Camera stuck at silt						
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	8.0	0.6	8.0	4.0




Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
2	Upstream	UTFX		N3091



1, 00:00:55, 12.80 m

Settled deposits, fine, 50% cross-sectional area loss



2, 00:00:55, 12.80 m

Settled deposits, fine, 50% cross-sectional area loss



Section Inspection

Item No. 3	Insp. No. 1	Date 20/03/26	Time 8:48	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR UTFX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: UTF
Road:	Inspected Length: 9.00 m	Upstream Pipe Depth:
Location:	Total Length: 9.00 m	Downstream Node: SW01 C
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 03 07		
Recommendations:		

Scale:	1:78	Position [m]	Code	Observation	Photo	Grade			
Depth: m SW01 C									
			MH	Start node, manhole, reference: SW01 C					
			WL	Water level, 5% of the vertical dimension					
			RFJ	Roots, fine at joint		2			
			RM	Roots, mass, 75% cross-sectional area loss	1, 2	5			
			SA	Survey abandoned: Root Mass					
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	2	15.0	1.8	16.0	5.0



laser surveys
land, building and underground services

Laser Surveys Limited

Leigh Sinton Road, Malvern

Tel. 01886 833 173

worcester@lasersurveys.com

Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
3	Upstream	UTFX		N3091



1, 00:00:32, 8.60 m
Roots, mass, 75% cross-sectional area loss



2, 00:00:32, 8.60 m
Roots, mass, 75% cross-sectional area loss



Section Inspection

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
4	1	20/03/26	8:49	Not Specified	No Rain Or Snow	No	SW01 XX
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Ash		Van 3		Camera 3	Not Specified	Not Specified	Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: SW01 X
Road:	Inspected Length: 46.60 m	Upstream Pipe Depth:
Location:	Total Length: 46.60 m	Downstream Node: OFFSITE
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 03 54		
Recommendations:		

Scale:	1:404	Position [m]	Code	Observation	Photo	Grade			
Depth: m SW01 X 0.00 0.00 9.20 9.60 20.60 21.40 21.70 33.20 37.50 37.50 43.70 44.50 46.60									
			MH	Start node, manhole, reference: SW01 X					
			WL	Water level, 5% of the vertical dimension					
			DES	Settled deposits, fine, 5% cross-sectional area loss		3			
			JN	Junction at 3 o'clock, 100mm dia					
			DES	Settled deposits, fine, 5% cross-sectional area loss		3			
			JN	Junction at 3 o'clock, 100mm dia					
			DES	Settled deposits, fine, 5% cross-sectional area loss		3			
			JN	Junction at 3 o'clock, 100mm dia					
			B	Broken pipe from 12 o'clock to 4 o'clock	1	4			
			DES	Settled deposits, fine, 10% cross-sectional area loss		3			
			JN	Junction at 3 o'clock, 100mm dia					
			DES	Settled deposits, fine, 15% cross-sectional area loss	2	3			
			SA	Survey abandoned: Stuck at Silt					
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	80.0	1.7	80.0	4.0	5	2.0	0.2	10.0	3.0



Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
4	Downstream	SW01 XX		N3091



1, 00:01:34, 37.50 m
Broken pipe from 12 o'clock to 4 o'clock



2, 00:02:39, 44.50 m
Settled deposits, fine, 15% cross-sectional area loss



Section Inspection

Item No. 5	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW01 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction:	Downstream	Upstream Node:	FW01 X
Road:	Inspected Length:	35.10 m	Upstream Pipe Depth:	
Location:	Total Length:	35.10 m	Downstream Node:	OFFSITE
Surface Type:	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular	
Type of Pipe:		Dia/Height:	150 mm	
Flow Control:	No flow control	Material:	Vitrified clay	
Year Constructed:	Not Specified	Lining Type:	No Lining	
Inspection Purpose:	Routine inspection	Lining Material:	No Lining	
Comments:	Time 00 06 58			
Recommendations:				

Scale:	1:304	Position [m]	Code	Observation	Photo	Grade
Depth: m FW01 X 0.00 0.00 26.30 26.90 35.10 Offsite Depth: m						

Section Inspection

Item No. 6	Insp. No. 1	Date 20/03/26	Time 8:49	Client`s Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW02X
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:		Inspection Direction: Upstream		Upstream Node: FW02	
Road:		Inspected Length: 2.90 m		Upstream Pipe Depth:	
Location:		Total Length: 2.90 m		Downstream Node: FW01 B	
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:		Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Vitrified clay		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		
Comments:	Time 00 08 43				
Recommendations:					

Scale: 1:50
Position [m]
Code
Observation
Photo
Grade

Depth: m
FW01 B

0.00

0.00

2.90

FW02
Depth: m

MH Start node, manhole, reference: FW01 B

WL Water level, 5% of the vertical dimension

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection

Item No. 7	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: BUILDING
Road:	Inspected Length: 1.00 m	Upstream Pipe Depth:
Location:	Total Length: 1.00 m	Downstream Node: FW03 B
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 09 10		
Recommendations:		

</

Section Inspection

Item No. 8	Insp. No. 1	Date 20/03/26	Time 8:49	Client`s Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:		Inspection Direction: Upstream		Upstream Node:	BUILDING
Road:		Inspected Length: 1,000.00 m		Upstream Pipe Depth:	
Location:		Total Length: 1.00 m		Downstream Node:	FW03 C
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul			Pipe Shape:	Circular
Type of Pipe:				Dia/Height:	100 mm
Flow Control:	No flow control			Material:	Vitrified clay
Year Constructed:	Not Specified			Lining Type:	No Lining
Inspection Purpose:	Routine inspection			Lining Material:	No Lining
Comments:	Time 00 09 30				
Recommendations:					

[illegible]



Section Inspection

Item No. 9	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: BUILDING
Road:	Inspected Length: 1.30 m	Upstream Pipe Depth:
Location:	Total Length: 1.30 m	Downstream Node: FW04 B
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 09 49		
Recommendations:		

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW04 B



Section Inspection

Item No. 10	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction:	Upstream	Upstream Node:	BUILDING
Road:	Inspected Length:	1.40 m	Upstream Pipe Depth:	
Location:	Total Length:	1.40 m	Downstream Node:	FW04 C
Surface Type:	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular	
Type of Pipe:		Dia/Height:	100 mm	
Flow Control:	No flow control	Material:	Vitrified clay	
Year Constructed:	Not Specified	Lining Type:	No Lining	
Inspection Purpose:	Routine inspection	Lining Material:	No Lining	
Comments:	Time 00 10 10			
Recommendations:				

Scale:1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW04 C

<



Section Inspection

Item No. 11	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction:	Upstream	Upstream Node:	BUILDING
Road:	Inspected Length:	1.40 m	Upstream Pipe Depth:	
Location:	Total Length:	1.40 m	Downstream Node:	FW05 B
Surface Type:	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular	
Type of Pipe:		Dia/Height:	100 mm	
Flow Control:	No flow control	Material:	Vitrified clay	
Year Constructed:	Not Specified	Lining Type:	No Lining	
Inspection Purpose:	Routine inspection	Lining Material:	No Lining	
Comments:	Time 00 10 28			
Recommendations:				

Scale:	1:50	Position [m]	Code	Observation	Photo	Grade
Depth: m FW05 B Building Depth: m						



Section Inspection

Item No. 12	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node:	BUILDING
Road:	Inspected Length: 1.30 m	Upstream Pipe Depth:	
Location:	Total Length: 1.30 m	Downstream Node:	FW05 C
Surface Type:	Joint Length:	Downstream Pipe Depth:	
Use: Foul	Pipe Shape: Circular		
Type of Pipe:	Dia/Height: 100 mm		
Flow Control: No flow control	Material: Vitrified clay		
Year Constructed: Not Specified	Lining Type: No Lining		
Inspection Purpose: Routine inspection	Lining Material: No Lining		
Comments: Time 00 10 51			
Recommendations:			

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW05 C

MH

Start node, manhole, reference: FW05 C

WL

Water level, 5% of the vertical dimension

LU

Line deviates up

REM

General remark: Survey finished at Line Up

Building

Depth: m

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0



Section Inspection

Item No. 13	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: BUILDING
Road:	Inspected Length: 1.00 m	Upstream Pipe Depth:
Location:	Total Length: 1.00 m	Downstream Node: FW06 B
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 11 11		
Recommendations:		

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW06 B

0.00

0.00

1.00

1.00

Building

Depth: m

MH

Start node, manhole, reference: FW06 B

WL

Water level, 5% of the vertical dimension

LU

Line deviates up

REM

General remark: Survey finished at Line Up

STR No. Def

STR Peak

STR Mean

STR Total

STR Grade

SER No. Def

SER Peak

SER Mean

SER Total

SER Grade

0

0.0

0.0

0.0

0.0

0

0.0

0.0

0.0

0.0



Section Inspection

Item No. 14	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: BUILDING
Road:	Inspected Length: 1.00 m	Upstream Pipe Depth:
Location:	Total Length: 1.00 m	Downstream Node: FW06 C
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 11 32		
Recommendations:		

Scale:	1:50	Position [m]	Code	Observation	Photo	Grade
Depth: m FW06 C Building Depth: m						



Section Inspection

Item No. 15	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: BUILDING
Road:	Inspected Length: 1.10 m	Upstream Pipe Depth:
Location:	Total Length: 1.10 m	Downstream Node: FW07 B
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 11 51		
Recommendations:		

Scale:	1:50	Position [m]	Code	Observation	Photo	Grade																				
Depth: m FW07 B 0.00 0.00 1.10 1.10 Building Depth: m <table><tr><th>STR No. Def</th><th>STR Peak</th><th>STR Mean</th><th>STR Total</th><th>STR Grade</th><th>SER No. Def</th><th>SER Peak</th><th>SER Mean</th><th>SER Total</th><th>SER Grade</th></tr><tr><td>0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0.0</td></tr></table>							STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade	0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																	
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																	
			MH	Start node, manhole, reference: FW07 B																						
			WL	Water level, 5% of the vertical dimension																						
			LU	Line deviates up																						
			REM	General remark: Survey finished at Line Up																						



Section Inspection

Item No. 16	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction:	Upstream	Upstream Node:	BUILDING
Road:	Inspected Length:	1.10 m	Upstream Pipe Depth:	
Location:	Total Length:	1.10 m	Downstream Node:	FW07 C
Surface Type:	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular	
Type of Pipe:		Dia/Height:	100 mm	
Flow Control:	No flow control	Material:	Vitrified clay	
Year Constructed:	Not Specified	Lining Type:	No Lining	
Inspection Purpose:	Routine inspection	Lining Material:	No Lining	
Comments:	Time 00 12 10			
Recommendations:				

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW07 C

0.00

MH

Start node, manhole, reference: FW07 C

0.00

WL

Water level, 5% of the vertical dimension

1.10

LU

Line deviates up

1.10

REM

General remark: Survey finished at Line Up

Building

Depth: m

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0



worcester@lasersurveys.com

Item No. 17	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:		Inspection Direction: Upstream		Upstream Node: BUILDING	
Road:		Inspected Length: 1.20 m		Upstream Pipe Depth:	
Location:		Total Length: 1.20 m		Downstream Node: FW08 C	
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul			Pipe Shape:	Circular
Type of Pipe:				Dia/Height:	100 mm
Flow Control:	No flow control			Material:	Vitrified clay
Year Constructed:	Not Specified			Lining Type:	No Lining
Inspection Purpose:	Routine inspection			Lining Material:	No Lining
Comments:	Time 00 12 27				
Recommendations:					

Scale: 1:50
Position [m]
Code
Observation
Photo
Grade

MH	Start node, manhole, reference: FW08 C
WL	Water level, 5% of the vertical dimension
LU	Line deviates up
REM	General remark: Survey finished at Line Up

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0



Section Inspection

Item No. 18	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW09X
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:		Inspection Direction: Upstream		Upstream Node: FW09	
Road:		Inspected Length: 11.50 m		Upstream Pipe Depth:	
Location:		Total Length: 11.50 m		Downstream Node: FW08 B	
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul			Pipe Shape:	Circular
Type of Pipe:				Dia/Height:	100 mm
Flow Control:	No flow control			Material:	Vitrified clay
Year Constructed:	Not Specified			Lining Type:	No Lining
Inspection Purpose:	Routine inspection			Lining Material:	No Lining
Comments:	Time 00 12 48				
Recommendations:					

Scale:	1:100	Position [m]		Code	Observation	Photo	Grade
Depth: m FW08 B </							



Section Inspection

Item No. 19	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR OFFSITEX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node:	OFFSITE
Road:	Inspected Length: 4.60 m	Upstream Pipe Depth:	
Location:	Total Length: 4.60 m	Downstream Node:	FW10 B
Surface Type:	Joint Length:	Downstream Pipe Depth:	
Use: Foul	Pipe Shape: Circular		
Type of Pipe:	Dia/Height: 100 mm		
Flow Control: No flow control	Material: Vitrified clay		
Year Constructed: Not Specified	Lining Type: No Lining		
Inspection Purpose: Routine inspection	Lining Material: No Lining		
Comments: Time 00 13 40			
Recommendations:			

Scale:	1:50	Position [m]	Code	Observation	Photo	Grade																				
Depth: m FW10 B 0.00 MH Start node, manhole, reference: FW10 B 0.00 WL Water level, 5% of the vertical dimension 2.30 JN Junction at 9 o'clock, 100mm dia 4.60 MHF Finish node, manhole, reference: Offsite Offsite Depth: m <table><tr><th>STR No. Def</th><th>STR Peak</th><th>STR Mean</th><th>STR Total</th><th>STR Grade</th><th>SER No. Def</th><th>SER Peak</th><th>SER Mean</th><th>SER Total</th><th>SER Grade</th></tr><tr><td>0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>1.0</td><td>0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>1.0</td></tr></table>							STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade	0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																	
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0																	



Section Inspection

Item No. 20	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR OFFSITEX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction:	Upstream	Upstream Node:	OFFSITE
Road:	Inspected Length:	14.50 m	Upstream Pipe Depth:	
Location:	Total Length:	14.50 m	Downstream Node:	FW10 A
Surface Type:	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular	
Type of Pipe:		Dia/Height:	100 mm	
Flow Control:	No flow control	Material:	Vitrified clay	
Year Constructed:	Not Specified	Lining Type:	No Lining	
Inspection Purpose:	Routine inspection	Lining Material:	No Lining	
Comments:	Time 00 14 08			
Recommendations:				

Scale:	1:126	Position [m]	Code	Observation	Photo	Grade
Depth: m FW10 A <						



Section Inspection

Item No. 21	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW10 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: FW10 X
Road:	Inspected Length: 2.30 m	Upstream Pipe Depth:
Location:	Total Length: 2.30 m	Downstream Node: FW08
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 14 50		
Recommendations:		

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW10 X

0.00

0.00

2.30

FW08

Depth: m

MH

Start node, manhole, reference: FW10 X

WL

Water level, 5% of the vertical dimension

MHF

Finish node, manhole, reference: FW08

STR No. Def

STR Peak

STR Mean

STR Total

STR Grade

SER No. Def

SER Peak

SER Mean

SER Total

SER Grade

0

0.0

0.0

0.0

1.0

0

0.0

0.0

0.0

1.0



Section Inspection

Item No. 22	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW08 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:		Inspection Direction: Upstream		Upstream Node: FW08 X	
Road:		Inspected Length: 1.30 m		Upstream Pipe Depth:	
Location:		Total Length: 1.30 m		Downstream Node: FW07	
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul			Pipe Shape:	Circular
Type of Pipe:				Dia/Height:	150 mm
Flow Control:	No flow control			Material:	Vitrified clay
Year Constructed:	Not Specified			Lining Type:	No Lining
Inspection Purpose:	Routine inspection			Lining Material:	No Lining
Comments:	Time 00 15 14				
Recommendations:					

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW07

0.00

0.00

1.30

FW08 X

Depth: m

0.00

0.00

1.30

MH

WL

MHF

Start node, manhole, reference: FW07

Water level, 5% of the vertical dimension

Finish node, manhole, reference: FW08 X

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection

Item No. 23	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW07 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: FW07 X
Road:	Inspected Length: 0.90 m	Upstream Pipe Depth:
Location:	Total Length: 0.90 m	Downstream Node: FW06
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 150 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 15 36		
Recommendations:		

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW07 X

0.00

MH

Start node, manhole, reference: FW07 X

0.00

WL

Water level, 5% of the vertical dimension

0.90

MHF

Finish node, manhole, reference: FW06

FW06

Depth: m

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection

Item No. 24	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW06 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction:	Downstream	Upstream Node:	FW06 X
Road:	Inspected Length:	3.80 m	Upstream Pipe Depth:	
Location:	Total Length:	3.80 m	Downstream Node:	FW05
Surface Type:	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular	
Type of Pipe:		Dia/Height:	150 mm	
Flow Control:	No flow control	Material:	Vitrified clay	
Year Constructed:	Not Specified	Lining Type:	No Lining	
Inspection Purpose:	Routine inspection	Lining Material:	No Lining	
Comments:	Time 00 15 54			
Recommendations:				

Scale:	1:50	Position [m]	Code	Observation	Photo	Grade
Depth: m FW06 X						



Section Inspection

Item No. 25	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW05 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction:	Downstream	Upstream Node:	FW05 X
Road:	Inspected Length:	1.30 m	Upstream Pipe Depth:	
Location:	Total Length:	1.30 m	Downstream Node:	FW04
Surface Type:	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular	
Type of Pipe:		Dia/Height:	150 mm	
Flow Control:	No flow control	Material:	Vitrified clay	
Year Constructed:	Not Specified	Lining Type:	No Lining	
Inspection Purpose:	Routine inspection	Lining Material:	No Lining	
Comments:	Time 00 16 21			
Recommendations:				

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW05 X

0.00

0.00

1.30

FW04

Depth: m

MH

Start node, manhole, reference: FW05 X

WL

Water level, 5% of the vertical dimension

MHF

Finish node, manhole, reference: FW04


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection

Item No. 26	Insp. No. 1	Date 20/03/26	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW04 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: FW04 X
Road:	Inspected Length: 0.80 m	Upstream Pipe Depth:
Location:	Total Length: 0.80 m	Downstream Node: FW03
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 150 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 16 40		
Recommendations:		

Scale:	1:50	Position [m]	Code	Observation	Photo	Grade
Depth: m FW04 X  MH Start node, manhole, reference: FW04 X WL Water level, 5% of the vertical dimension MHF Finish node, manhole, reference: FW03						



Section Inspection

Item No. 27	Insp. No. 1	Date 20/03/26	Time 8:50	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR FW03 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: FW03 X
Road:	Inspected Length: 1.50 m	Upstream Pipe Depth:
Location:	Total Length: 1.50 m	Downstream Node: FW01
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Foul	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 150 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 16 59		
Recommendations:		

Scale: 1:50

Position [m]

Code

Observation

Photo

Grade

Depth: m

FW03 X

0.00

0.00

1.50

FW01

Depth: m

MH

Start node, manhole, reference: FW03 X

WL

Water level, 5% of the vertical dimension

MHF

Finish node, manhole, reference: FW01

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection

Item No. 28	Insp. No. 1	Date 20/03/26	Time 8:50	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR SW02 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: SW02 X
Road:	Inspected Length: 16.90 m	Upstream Pipe Depth:
Location:	Total Length: 16.90 m	Downstream Node: SW04
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 150 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 17 18		
Recommendations:		

Scale:	1:147	Position [m]	Code	Observation	Photo	Grade
Depth: m SW02 X						



Section Inspection

Item No. 29	Insp. No. 1	Date 20/03/26	Time 8:50	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR SW03X
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: SW03
Road:	Inspected Length: 5.40 m	Upstream Pipe Depth:
Location:	Total Length: 5.40 m	Downstream Node: SW02 A
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 150 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 18 54		
Recommendations:		

Scale: 1:50	Position [m]	Code	Observation	Photo	Grade
Depth: m SW02 A					
	0.00	MH	Start node, manhole, reference: SW02 A		
	0.00	WL	Water level, 5% of the vertical dimension		
	4.60	JDM	Joint displaced, medium		1 / 3
	5.40	CPF	Finish node, catchpit, reference: SW03		
SW03 Depth: m					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	1.0	0.2	1.0	1.0	1	2.0	0.4	2.0	3.0



Section Inspection

Item No. 30	Insp. No. 1	Date 20/03/26	Time 8:50	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR BUILDINGX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:		Inspection Direction: Upstream		Upstream Node: BUILDING	
Road:		Inspected Length: 13.60 m		Upstream Pipe Depth:	
Location:		Total Length: 13.60 m		Downstream Node: FW09 A	
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:		Circular	
Type of Pipe:		Dia/Height:		100 mm	
Flow Control:	No flow control	Material:		Polyvinyl chloride	
Year Constructed:	Not Specified	Lining Type:		No Lining	
Inspection Purpose:	Routine inspection	Lining Material:		No Lining	
Comments:	Time 00 19 24				
Recommendations:					

Scale:	1:118	Position [m]	Code	Observation	Photo	Grade																				
Depth: m FW09 A 0.00 0.00 0.25 0.80 2.70 13.50 13.60 13.60 JN S01 F01 REM MH WL LL Junction at 9 o'clock, 100mm dia Settled deposits, fine, 5% cross-sectional area loss, start Settled deposits, fine, 5% cross-sectional area loss, finish Line deviates up General remark: Survey finished at Line Up <table><tr><th>STR No. Def</th><th>STR Peak</th><th>STR Mean</th><th>STR Total</th><th>STR Grade</th><th>SER No. Def</th><th>SER Peak</th><th>SER Mean</th><th>SER Total</th><th>SER Grade</th></tr><tr><td>0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0.0</td></tr></table>							STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade	0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																	
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																	



Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
31	Upstream	UTFX		N3091



1, 00:00:14, 3.00 m


Settled deposits, hard or compacted, 75% cross-sectional area loss



Section Inspection

Item No. 32	Insp. No. 1	Date 20/03/26	Time 8:50	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned No	PLR SW04 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified


Town or Village:	Inspection Direction: Downstream	Upstream Node: SW04 X
Road:	Inspected Length: 8.20 m	Upstream Pipe Depth:
Location:	Total Length: 8.20 m	Downstream Node: SW05
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 150 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Time 00 20 37 / End of Vid001 @ 00 21 27		
Recommendations:		

Scale:	1:71	Position [m]	Code	Observation	Photo	Grade			
Depth: m SW04 X  0.00 MH Start node, manhole, reference: SW04 X 0.00 WL Water level, 5% of the vertical dimension 0.25 LL Line deviates left 8.20 CPF Finish node, catchpit, reference: SW05 SW05 Depth: m									
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Inspection

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
33	1	15/06/26	11:34	Not Specified	No Rain Or Snow	Yes	SW01 XX
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Ash		Van 3		Camera 3	Not Specified	Not Specified	Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: SW01 X
Road:	Inspected Length: 45.70 m	Upstream Pipe Depth:
Location:	Total Length: 45.70 m	Downstream Node: CW01
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	
Comments: Start of Vid-002 @ 00 00 00		
Recommendations:		

Scale:	1:396	Position [m]	Code	Observation	Photo	Grade																				
Depth: m SW01 X  CW01 Depth: m <table><tr><th>STR No. Def</th><th>STR Peak</th><th>STR Mean</th><th>STR Total</th><th>STR Grade</th><th>SER No. Def</th><th>SER Peak</th><th>SER Mean</th><th>SER Total</th><th>SER Grade</th></tr><tr><td>0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0</td><td>0.0</td><td>0.0</td><td>0.0</td><td>0.0</td></tr></table>							STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade	0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade																	
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0																	
	0.00	MH	Start node, manhole, reference: SW01 X																							
	0.00	WL	Water level, 5% of the vertical dimension																							
	0.30	CM	Cracks, multiple from 12 o'clock to 5 o'clock																							
	0.70	FL	Fracture, longitudinal at 12 o'clock																							
	1.80	DEEJ	Attached deposits, encrustation at joint from 7 o'clock to 11 o'clock, 5% cross-sectional area loss																							
	9.90	JN	Junction at 3 o'clock, 100mm dia																							
	21.80	JN	Junction at 3 o'clock, 100mm dia																							
	33.60	JN	Junction at 3 o'clock, 100mm dia																							
	37.60	B	Broken pipe from 12 o'clock to 5 o'clock	1																						
	43.95	JN	Junction at 3 o'clock, 100mm dia																							
	45.70	REM	General remark: Camera reached operating limits																							



laser surveys
land, building and underground services

Laser Surveys Limited

Leigh Sinton Road, Malvern

Tel. 01886 833 173

worcester@lasersurveys.com

Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
33	Downstream	SW01 XX		N3091



1, 00:02:31, 37.60 m
Broken pipe from 12 o'clock to 5 o'clock



Section Inspection

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
34	1	15/06/26	11:35	Not Specified	No Rain Or Snow	Yes	GULLYX
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Ash		Van 3		Camera 3	Not Specified	Not Specified	Not Specified

Town or Village:		Inspection Direction: Upstream		Upstream Node: GULLY	
Road:		Inspected Length: 27.00 m		Upstream Pipe Depth:	
Location:		Total Length: 27.00 m		Downstream Node: SW01 A	
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use: Surface water		Pipe Shape: Circular			
Type of Pipe:		Dia/Height: 100 mm			
Flow Control: No flow control		Material: Vitrified clay			
Year Constructed: Not Specified		Lining Type: No Lining			
Inspection Purpose: Routine inspection		Lining Material: No Lining			

Comments:

Recommendations:

Scale: 1:234	Position [m]	Code	Observation	Photo	Grade
Depth: m SW01 A					
	0.00	MH	Start node, manhole, reference: SW01 A		
	0.00	WL	Water level, 5% of the vertical dimension		
	0.50	JDM	Joint displaced, medium		1 / 3
	0.50	LL	Line deviates left		
	1.00	JN	Junction at 9 o'clock, 100mm dia		
	1.00	DES	Settled deposits, fine, 10% cross-sectional area loss		3
	2.60	S01	DES Settled deposits, fine, 5% cross-sectional area loss, start		
	4.60	F01	DES Settled deposits, fine, 5% cross-sectional area loss, finish		3
	10.20	DES	Settled deposits, fine, 5% cross-sectional area loss		3
	12.90	DEEJ	Attached deposits, encrustation at joint from 12 o'clock to 12 o'clock, 10% cross-sectional area loss	1	3
	13.40	JN	Junction at 9 o'clock, 100mm dia		
	21.70	DEEJ	Attached deposits, encrustation at joint from 8 o'clock to 5 o'clock, 5% cross-sectional area loss		3
	25.50	DEEJ	Attached deposits, encrustation at joint from 12 o'clock to 12 o'clock, 10% cross-sectional area loss		3
	26.90	DEC	Settled deposits, hard or compacted, 35% cross-sectional area loss	2	4
	27.00	SA	Survey abandoned: Compacted Debris		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	1.0	0.0	1.0	1.0	8	5.0	0.8	21.0	4.0



Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
34	Upstream	GULLYX		N3091



1, 00:00:53, 12.90 m

Attached deposits, encrustation at joint from 12 o'clock to 12 o'clock, 10% cross-sectional area loss



2, 00:01:44, 26.90 m

Settled deposits, hard or compacted, 35% cross-sectional area loss



Section Inspection

Item No. 35	Insp. No. 1	Date 15/06/26	Time 11:35	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR GULLYX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: GULLY
Road:	Inspected Length: 26.20 m	Upstream Pipe Depth:
Location:	Total Length: 26.20 m	Downstream Node: SW01 B
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	

Comments:

Recommendations:

Scale: 1:227	Position [m]	Code	Observation	Photo	Grade
Depth: m SW01 B 0.00 MH Start node, manhole, reference: SW01 B 0.00 WL Water level, 5% of the vertical dimension 0.50 LL Line deviates left 0.50 CC Crack, circumferential from 9 o'clock to 3 o'clock 2 / 2 1.50 DEEJ Attached deposits, encrustation at joint from 7 o'clock to 12 o'clock, 5% cross-sectional area loss 3 4.80 JN Junction at 3 o'clock, 100mm dia 5.30 DEEJ Attached deposits, encrustation at joint from 12 o'clock to 12 o'clock, 5% cross-sectional area loss 3 6.50 DEEJ Attached deposits, encrustation at joint from 8 o'clock to 4 o'clock, 5% cross-sectional area loss 3 12.90 DEEJ Attached deposits, encrustation at joint from 3 o'clock to 9 o'clock, 20% cross-sectional area loss 1 3 16.30 DEEJ Attached deposits, encrustation at joint from 3 o'clock to 9 o'clock, 15% cross-sectional area loss 2 3 17.60 JN Junction at 3 o'clock, 100mm dia 26.20 GYF Finish node, gully, reference: Gully Gully Depth: m					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	10.0	0.4	10.0	2.0	6	2.0	0.4	11.0	3.0




Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
35	Upstream	GULLYX		N3091



1, 00:00:47, 12.90 m

Attached deposits, encrustation at joint from 3 o'clock to 9 o'clock, 20% cross-sectional area loss



2, 00:01:12, 16.30 m

Attached deposits, encrustation at joint from 3 o'clock to 9 o'clock, 15% cross-sectional area loss



Section Inspection

Item No. 36	Insp. No. 1	Date 15/06/26	Time 11:35	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR UTFX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction:	Upstream	Upstream Node:	UTF
Road:	Inspected Length:	10.00 m	Upstream Pipe Depth:	
Location:	Total Length:	10.00 m	Downstream Node:	SW01 C
Surface Type:	Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular	
Type of Pipe:		Dia/Height:	100 mm	
Flow Control:	No flow control	Material:	Vitrified clay	
Year Constructed:	Not Specified	Lining Type:	No Lining	
Inspection Purpose:	Routine inspection	Lining Material:	No Lining	

Comments:

Recommendations:

Scale:	1:87	Position [m]	Code	Observation	Photo	Grade
Depth: m SW01 C						



laser surveys
land, building and underground services

Laser Surveys Limited

Leigh Sinton Road, Malvern

Tel. 01886 833 173

worcester@lasersurveys.com

Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
36	Upstream	UTFX		N3091



1, 00:00:39, 9.20 m
Roots, mass, 80% cross-sectional area loss



Section Inspection

Item No. 37	Insp. No. 1	Date 15/06/26	Time 11:36	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SW01 X
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Upstream	Upstream Node: SW01
Road:	Inspected Length: 30.50 m	Upstream Pipe Depth:
Location:	Total Length: 30.50 m	Downstream Node: CW01 B
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 100 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	

Comments:

Recommendations:

Scale: 1:265	Position [m]	Code	Observation	Photo	Grade
Depth: m CW01 B SW01 Depth: m					
	0.00	MH	Start node, manhole, reference: CW01 B		
	0.00	WL	Water level, 5% of the vertical dimension		
	3.50	JN	Junction at 9 o'clock, 100mm dia		
	5.10	DES	Settled deposits, fine, 5% cross-sectional area loss		
	6.70	DES	Settled deposits, fine, 5% cross-sectional area loss		
	12.60	DEEJ	Attached deposits, encrustation at joint from 8 o'clock to 4 o'clock, 5% cross-sectional area loss		
	13.90	RFJ	Roots, fine at joint		
	15.50	JDM	Joint displaced, medium		
	16.60	JN	Junction at 9 o'clock, 100mm dia		
	17.50	DEEJ	Attached deposits, encrustation at joint from 12 o'clock to 12 o'clock, 5% cross-sectional area loss		
	21.30	JDM	Joint displaced, medium		
	25.60	JN	Junction at 9 o'clock, 100mm dia		
	30.40	DES	Settled deposits, fine, 5% cross-sectional area loss		
	30.50	JN	Junction at 9 o'clock, 100mm dia		
	30.50	REM	General remark: Meters covered		

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	0.0	0	0.0	0.0	0.0	0.0

Section Inspection

Item No. 38	Insp. No. 1	Date 15/06/26	Time 11:35	Client`s Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR CW01 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:		Inspection Direction:	Downstream	Upstream Node:	CW01 X
Road:		Inspected Length:	16.50 m	Upstream Pipe Depth:	
Location:		Total Length:	16.50 m	Downstream Node:	CW02
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Combined	Pipe Shape:	Circular		
Type of Pipe:		Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Vitrified clay		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:143 Position [m] Code Observation Photo Grade

Code	Observation
MH	Start node, manhole, reference: CW01 X
WL	Water level, 5% of the vertical dimension

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection

Item No. 39	Insp. No. 1	Date 15/06/26	Time 11:36	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SW06 XX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: SW06 X
Road:	Inspected Length: 6.50 m	Upstream Pipe Depth:
Location:	Total Length: 6.50 m	Downstream Node: SW07
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 150 mm	
Flow Control: No flow control	Material: Vitrified clay	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose: Routine inspection	Lining Material: No Lining	

Comments:

Recommendations:

Scale: 1:57	Position [m]	Code	Observation	Photo	Grade
Depth: m SW06 X					
	0.00	CP	Start node, catchpit, reference: SW06 X		
	0.00	WL	Water level, 5% of the vertical dimension		
	0.20	RM	Roots, mass, 15% cross-sectional area loss	1	3
	4.10	JDM	Joint displaced, medium		1 / 3
	5.00	RM	Roots, mass, 10% cross-sectional area loss		3
	6.50	SKF	Finish node, soakaway, reference: SW07		
SW07 Depth: m					

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	1.0	0.2	1.0	1.0	3	4.0	1.5	10.0	3.0



laser surveys
land, building and underground services

Laser Surveys Limited

Leigh Sinton Road, Malvern

Tel. 01886 833 173

worcester@lasersurveys.com

Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
39	Downstream	SW06 XX		N3091



1, 00:00:11, 0.20 m
Roots, mass, 15% cross-sectional area loss



Section Inspection

Item No. 40	Insp. No. 1	Date 15/06/26	Time 11:36	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR GULLYX
Operator Ash		Vehicle Van 3		Camera Camera 3	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:		Inspection Direction: Upstream		Upstream Node: GULLY	
Road:		Inspected Length: 7.20 m		Upstream Pipe Depth:	
Location:		Total Length: 7.20 m		Downstream Node: SW06 A	
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water			Pipe Shape:	Circular
Type of Pipe:				Dia/Height:	150 mm
Flow Control:	No flow control			Material:	Vitrified clay
Year Constructed:	Not Specified			Lining Type:	No Lining
Inspection Purpose:	Routine inspection			Lining Material:	No Lining

Comments:

Recommendations:

Scale: 1:63	Position [m]	Code	Observation	Photo	Grade
Depth: m SW06 A					
0.00	CP	Start node, catchpit, reference: SW06 A			
0.00	WL	Water level, 5% of the vertical dimension			
0.25	JN	Junction at 3 o'clock, 100mm dia			
2.20	JDM	Joint displaced, medium			1 / 3
6.00	JDM	Joint displaced, medium			1 / 3
6.25	JN	Junction at 9 o'clock, 100mm dia			
7.10	LL	Line deviates left			
7.20	RM	Roots, mass, 35% cross-sectional area loss		1	5
7.20	SA	Survey abandoned: Camera stuck at root mass			

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
2	1.0	0.3	2.0	1.0	3	10.0	1.9	14.0	5.0



laser surveys
land, building and underground services

Laser Surveys Limited

Leigh Sinton Road, Malvern

Tel. 01886 833 173

worcester@lasersurveys.com

Section Pictures

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
40	Upstream	GULLYX		N3091



1, 00:00:46, 7.20 m

Roots, mass, 35% cross-sectional area loss


APPENDIX C – ARCHITECTURAL PROPOSALS

Worthing High School





Site Plan

Option 1



APPENDIX C – DRAINAGE LAYOUT DRAWING



- | LEGEND | |
|---|--|
|  | PROPOSED SURFACE WATER DRAIN |
|  | EXISTING SURFACE WATER DRAIN |
|  | EXISTING SURFACE WATER DRAIN TO BE ABANDONED |
|  | EXISTING FOUL WATER DRAIN |
|  | PROPOSED PLASTIC INSPECTION CHAMBER (PPIC) |
|  | EXISTING MANHOLE |
|  | YARD/BINSTORE GULLY |
|  | RAIN WATER PIPE |
|  | PROPOSED CHANNEL DRAIN |
|  | SITE BOUNDARY |

