Non Material Minor Amendment to
AWDM/0366/13
New office to Rear Of 4 To 14 Southview Road
Southwick Brighton West Sussex BN42 4TU

4/5/16

South Boundary Wall as shown in following photos is in poor condition and inferior quality.
Proposal is to rebuild as shown on engineers drawings in Freshfield Lane Multi stock Facings (shown below)



circle 25
design & planning









circle 25

design & planning


FFL 8·800





