

Drainage Verification Report

Land formerly Eastbrook Primary School, Southwick, BN42 4N

Client

Lovell Partnerships

Ref: 11650
Date: March 2025

Consulting Engineers

GTA Civils & Transport Limited
Maple House
192-198 London Road
Burgess Hill
West Sussex, RH15 9RD
Tel: 01444 871444

Index

Executive Summary

1 Introduction 2

2 Driveways 3

3 Conclusion 4

Schedule of Appendices

A As-Built drawings

B Manhole pictures

C Soakaway Installation

D CCTV Survey

Issue	Issue date	Compiled	Checked
Preliminary Issue	21st March 2025	MB	MR

Report by: Martin Burchell – Associate Director/Senior Engineer
Checked by: Martin Roberts I Eng, ACIWEM, MCIHT

1 Introduction

1.1 This report has been prepared for Lovell in relation to the site 'Land formerly Eastbrook Primary School, Southwick, BN42 4N'. No responsibility is accepted to any third party for all or part of this study in connection with this or any other development.

1.2 GTA Civils & Transport Limited was appointed by Lovell Partnerships to provide a Drainage Verification Report as required by Adur District Council to discharge planning condition 10 of the consent, as listed on planning approval reference: **AWDM/0585/22**. This is as follows:

10. Drainage: verification

Immediately following completion of the approved surface water drainage system and prior to occupation of any part of the development, the developer/applicant shall provide the local planning authority with as-built drawings of the implemented scheme together with a completion report prepared by a qualified engineer that confirms that the scheme was built in accordance with the approved drawing/s and is fit for purpose. The scheme shall thereafter be maintained in perpetuity.

1.3 This report will provide evidence of compliance in accordance with condition 10 of the approved planning consent.

1.4 The sewers inspected for this report to remain private and maintained by an appointed management company.

2 Driveways

Figure 2 - Plot 1



Figure 1 - Plot 2



Figure 3 - Plot 6



Figure 4 - Plot 6



3 Conclusion

3.1 The developer has confirmed that all proposed drainage has been installed in accordance with GTA Civils & Transport's construction issue drawings. Refer to below extract from email confirmation.

- End of Report -

Appendix A


N
SIC
CL 14.40
IL 13.60
SWD 100ø 12.01m 1:60
RP
CL14.40
IL13.85
SIC1
CL 14.285
IL 13.440
SWD 100ø 2.03m 1:47
FIC
CL14.25
IL13.65
FFL
14.400
Plot 1
Plot 2
Plot 3
Plot 4
FIC
CL14.38
IL13.65
FIC
CL14.38
IL13.65
SWD 100ø 4.47m 1:37
RG
SMH1
13500
CL 14.165
IL 13.200
Type C
4.0m
FROM EDGE
OF PIPE
EXISTING SEWER EASEMENT
FIC
CL14.25
IL13.65
FWD 100ø 23.56m 1:76
FIC
CL14.30
IL13.65
FAC
CL14.37
IL13.77
FAC
CL14.37
IL13.77
SAC
CL 14.30
IL 13.70
SWD 100ø 8.51m 1:93
SWD 100ø 1:7
FIC
CL14.25
IL13.65
FIC
CL14.250
IL13.300
FFL
14.400
ALL PRIVATE DRIVES TO BE PERMEABLE
PAVED WITH MIN. 250mm THICK 30%
VOIDED STONE SUB-BASE.
RP
CL14.375
IL13.725
FFL
14.550
Plot 5
Plot 6
Plot 7
Plot 8
SWD 100ø 10.61m 1:52
SIC
CL 14.350
IL 13.520
100ø 5.63m 1:80
FIC
CL14.50
IL13.75
FWD 100ø 6.97m 1:47
FIC
CL14.53
IL13.65
FIC
CL14.53
IL13.70
FIC
CL14.68
IL13.85
FIC
CL14.470
IL13.450
SIC
CL14.436
IL13.700
SIC
CL 14.285
IL 13.600
SIC14
CL 14.325
IL 13.400
RP
CL14.550
IL14.100
SWD 100ø 15.2m 1:37
FFL
14.550
FFL
14.700
FIC
CL14.69
IL13.85
FIC
CL14.69
IL13.85
100ø 19.11m 1:35
SIC
CL14.642
IL13.860
RP
CL14.700
IL14.250
SWD 100ø 14.47m 1:37
FFL
14.700
FFL
14.850
FIC
CL14.85
IL14.05
FIC
CL14.83
IL14.05
100ø 2.48m 1:40
FIC
CL14.80
IL13.90
SIC
CL14.835
IL14.120
SWD 100ø 15.58m 1:75
FFL
14.850
FFL
15.000
RW 0.15m
CHANNEL DRAIN
RW 0.15m
RP
CL14.750
IL14.300
RP
CL14.950
IL14.500
FIC
CL14.97
IL14.05
FWD 100ø 6.26m 1:63
FIC
CL14.98
IL14.20
FIC
CL14.98
IL14.25
SWD 100ø 9.42m 1:64
SIC
CL 14.900
IL 14.300
SWD 100ø 9.21m 1:60
ROAD ON EITHER SIDE
OF CENTRAL LANDSCAPE
AREA TO DRAIN
DIRECTLY INTO SWALES
FWMH6
13500
CL13.085
IL12.477
Type C
SWD 150ø 114.5m 1:109
SCP3
18000 Catchpit
CL 14.151
IL in 12.900
IL out 12.745
SL 12.445
SMH16
13500
CL 14.178
IL 13.000
Type C
150ø 1:45
IL13.036
IL13.240
FWD 100ø 67.3m 1:80
SWD 100ø 5.13m 1:22
SWD 100ø 5.23m 1:16
IL13.465
SWD 150ø 43.34m 1:51
IL13.330
FWMH7
13500
CL14.736
IL13.368
Type C
SWD 100ø 6.55m 1:15
SWD 100ø 7.75m 1:12
SWD 100ø 5.45m 1:22
SMH14
13500
CL 14.774
IL 13.850
Type C
SIC10
CL 15.005
IL 14.200
RG
SIC
CL 14.650
IL 14.050
IL13.760
SWD 100ø 11.04m 1:80
RP
CL 14.750
IL 14.250
SAC9
CL 14.725
IL 13.950
SWD 100ø 6.6m 1:40
FIC
CL14.84
IL14.00
FIC
CL14.83
IL14.00
FIC
CL14.84
IL14.00
FFL
14.850
Plot 14
SMH13
13500
CL 14.569
IL 13.700
Type C
SWD 100ø 4.6m 1:30
SWD 100ø 4.39m 1:45
SIC
CL14.648
IL14.040
SWD 100ø 1:100
FIC
CL14.70
IL14.00
FIC
CL14.70
IL13.70
SWD 100ø 4.57m 1:43
SWD 100ø 1:80
FIC
CL14.70
IL14.00
FFL
14.850
RP
CL 14.690
IL 14.240
FWMH5
13500
CL14.516
IL12.992
Type C
FWD 100ø 8.6m 1:53
SWD 150ø 2158m 1:72
IL13.45
SMH9
13500
CL 14.556
IL 13.500
Type C
SWD 100ø 4.65m 1:17
FIC
CL14.84
IL14.00
FIC
CL14.75
IL14.00
FFL
14.850
SIC2
CL 14.75
IL 13.90
SWD 100ø 7.25m 1:73
SWD 100ø 11.16m 1:55
SIC
CL 14.55
IL 14.00
RP
CL 14.700
IL 14.250
SMH10
13500
CL 14.336
IL 13.200
Type C
100ø 1:100
SIC
CL14.42
IL13.310
SIC
CL 14.55
IL 13.70
SWD 100ø 1:13
SWD 100ø 1:80
SIC
CL 14.53
IL 13.75
TP01
SIC
CL 14.53
IL 13.80
TP02
Location of
soakaway tests -
February 2021
SWD 100ø 10.62m 1:90
SWD 100ø 9.26m 1:13
SMH6
13500
CL 14.251
IL 13.500
Type C
SWD 150ø 18.26m 1:41
IL12.45
IL12.67
FWD 150ø 53.6m 1:80
SMH7
13500
CL 13.904
IL 13.050
Type C
SWD 100ø 5.72m 1:25
SWD 150ø 1:13
SWD 150ø 1:13
SWD 225ø 1:37
FWMH2
13500
CL13.865
IL12.321
Type C
FWMH4
18000
CL13.756
IL10.650(TBC)
TYPE B
FWMH3
12000
CL13.874
IL12.200
Type B
FOUL CONNECTION VIA NEW
MANHOLE SUBJECT TO S106
APPROVAL BY SOUTHERN WATER.
IL OF NEW 150ø PIPE
CONNECTION: 11.250.
IL OF EXISTING SEWER TO BE
CONFIRMED PRIOR TO WORKS
COMMENCING
FOUL CONNECTION
PIPEWORK TO BE
VITRIFIED CLAY
SIC
CL 13.90
IL 13.40
SWD 100ø 9.46m 1:80
SWD 100ø 1:7
SWD 100ø 1:7
SWD 100ø 1:80
SWD 100ø 1:80
SWD 100ø 1:46
SIC
CL 14.30
IL 13.40
SIC3
CL14.00
IL13.30
FIC
CL14.23
IL13.37
FIC
CL14.23
IL13.30
100ø 8.66m 1:11
SIC
CL 14.25
IL 13.50
FIC
CL14.10
IL13.41
FIC
CL14.10
IL13.43
4.0m
FROM EDGE
OF PIPE
Existing Combined Sewer 750Ø
EXISTING SEWER EASEMENT
SWD 100ø 9.46m 1:80
SWD 100ø 1:80
SWD 100ø 1:80
SWD 100ø

GENERAL NOTES

1. The location, size, depth and identification of existing services that may be shown or referred to on this drawing have been assessed from non intrusive observations , record drawings or the like. The contractor shall safely carry out intrusive investigations, trial holes or soundings prior to commencing work to satisfy himself that it is safe to proceed and that the assessments are accurate. any discrepancies shall be notified to gta prior to works commencing.

2. Tender or billing drawings shall not be used for construction or the ordering of materials.

3. Do not scale. All dimensions and levels to be site confirmed.

4. This drawing shall be read in conjunction with all relevant architects, consultants drawings and specifications, together with H&S plan requirements

5. Copyright : This drawing must not be copied, amended nor reproduced without the prior written agreement of gta.

6. All drawings specifications and recommendations made by gta are subject to Local Authority and other relevant Statutory Authorities approval. Any works or services made abortive due to the client proceeding prior to these approvals is considered wholly at the Clients risk. gta hold no responsibility for resulting abortive works or costs.

Rev	Amendments	Date	Dsn	Chk
A1	AS BUILT ISSUE	20.03.25	MB	MR

PHASE: 0

MH No.	MANHOLE DIAMETER (mm)	MANHOLE TYPE	COVER LEVEL (m)	INVERT LEVEL (m)	DEPTH TO SOFFIT (m)	EASTING (m)	NORTHING (m)
SCP1	1800	CATCHPIT	14.172	12.745	1.202	524782.062	105525.258
SCP2	1800	CATCHPIT	14.031	12.770	1.111	524804.630	105514.946
SCP3	1800	CATCHPIT	14.151	12.745	1.181	524798.025	105526.547
SMH1	1350	Type C	14.165	13.200	0.815	524772.097	105549.048
SMH2	1350	Type C	14.012	13.000	0.862	524771.171	105530.498
SMH5	1350	Type C	13.916	12.895	0.796	524773.679	105519.189
SMH6	1350	Type C	14.351	13.500	0.701	524791.632	105510.881
SMH7	1350	Type C	13.904	13.050	0.704	524773.388	105511.761
SMH9	1350	Type C	14.556	13.500	0.906	524826.260	105509.138
SMH10	1350	Type C	14.336	13.200	0.986	524804.710	105510.259
SMH13	1350	Type C	14.569	13.700	0.719	524826.828	105518.213
SMH14	1350	Type C	14.774	13.850	0.774	524844.577	105527.479
SMH16	1350	Type C	14.178	13.000	1.028	524801.299	105529.863
FWMH2	1350	Type C	13.865	12.321	1.394	524771.487	105513.319
FWMH3	1200	Type B	13.874	12.200	1.524	524770.626	105509.718
FWMH4	1800	Type B	13.756	10.650	2.356	524766.702	105509.777
FWMH5	1350	Type C	14.516	12.992	1.374	524825.029	105510.682
FWMH6	1350	Type C	14.085	12.477	1.458	524772.593	105532.510
FWMH7	1350	Type C	14.736	13.368	1.268	524839.803	105529.167

DRAWING SUBJECT TO S104 APPROVAL FROM SOUTHERN WATER. ANY WORKS CARRIED OUT PRIOR TO WRITTEN APPROVAL ARE AT RISK.

REFER TO DRAINAGE LAYOUT DRAWING NO. 11650/1601

gta Civils & Transport
Maple House, 192-198 London Road,
Burgess Hill, West Sussex, RH15 9RD
Tel.01444 871444 Web: www.gtacivils.co.uk

Client: Gravity

Architect: AHMM

Project: LAND AT FORMER EASTBROOK PRIMARY SCHOOL

Title: Manhole Schedule

Status: AS BUILT

Date: FEBRUARY 2023

Scale @ A3: NTS

Drawing Number: 11650/1602

Rev.: A1

CLASS B GRANULAR BED



CONCRETE BED & SURROUND (C.B.S.)



DIMENSION Y = - IN ROCK, CONCRETE OR MIXED SOILS CONTAINING ROCK BANDS, BOULDERS, LARGE FLINTS OR STONES OR OTHER IRREGULAR HARD SPOTS THAT RESULT IN UNEVEN TRENCH BOTTOM Y=1/4 Bc OR 200 mm WHICH EVER IS THE GREATER, BUT NOT LESS THAN 50mm UNDER COLLARS

NOTES - IN SOILS THAT PERMIT AN EVEN TRENCH BOTTOM TO BE EXCAVATED Y=1/6 Bc OR 150 mm WHICH EVER IS GREATER, BUT NOT LESS THAN 50 mm UNDER COLLARS

1) FOR PIPES EXCEEDING 600 mm DIA REFER TO ENGINEER
2) IN WET OR SOFT GROUND SEEK GUIDANCE FROM ENGINEER
3)THE BEDDINGS MAY BE MODIFIED FOR CERTAIN SUB-SOIL CONDITIONS AT THE ENGINEERS DISCRETION
4) THE CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING ADDITIONAL PROTECTION IN AREAS SUBJECT TO LOADS FROM SITE TRAFFIC. THE CONTRACTOR SHALL IDENTIFY THESE ZONES AND RESTRICT TRAFFIC ELSEWHERE
5) SEE ALSO BS 8301
6) FOR GREATER TRENCH WIDTHS SEEK GUIDANCE FROM ENGINEER

PIPE SIZE	Bd TRENCH WIDTH
100 mm	0.6 m
150 mm	0.6 m
225 mm	0.7 m
300 mm	0.8 m
375 mm	1.1 m
400 mm	1.1 m
450 mm	1.2 m
500 mm	1.2 m
600 mm	1.4 m

GRANULAR MATERIAL	
PIPE SIZE	AGGREGATE
100 mm	10 mm SINGLE SIZE
150 mm	OR 14-5 mm GRADED 10,14,20 SINGLE SIZE OR
150 mm-500 mm	20-25 mm GRADED
600 mm	CRUSHED ROCK OR 40-45 mm GRADED

BEDDING DETAILS LANDSCAPE AREAS

CLASS B GRANULAR BED



Pipe Size	Trench Width
100 mm	0.6 m
150 mm	0.6 m
225 mm	0.7 m
300 mm	0.8 m
375 mm	1.1 m
400 mm	1.1 m
450 mm	1.2 m
500 mm	1.2 m
600 mm	1.4 m

CLASS S GRANULAR SURROUND



CONCRETE BED & SURROUND (C.B.S.)



GRANULAR MATERIAL	
PIPE SIZE	AGGREGATE
100 mm	10 mm SINGLE SIZE
150 mm	10 OR 14mm SINGLE SIZE OF 14-5 mm GRADED
150 mm-500 mm	10,14,20 SINGLE SIZE OR 20-25 mm GRADED
600 mm	10,14,20 OR 40 mm SINGLE CRUSHED ROCK OR 40-45 mm GRADED

DIMENSION Y = - IN ROCK, CONCRETE OR MIXED SOILS CONTAINING ROCK BANDS, BOULDERS, LARGE FLINTS OR STONES OR OTHER IRREGULAR HARD SPOTS THAT RESULT IN UNEVEN TRENCH BOTTOM Y=1/4 Bc OR 200 mm WHICH EVER IS THE GREATER, BUT NOT LESS THAN 50mm UNDER COLLARS

NOTES - IN SOILS THAT PERMIT AN EVEN TRENCH BOTTOM TO BE EXCAVATED Y=1/6 Bc OR 150 mm WHICH EVER IS GREATER, BUT NOT LESS THAN 50 mm UNDER COLLARS

1) FOR PIPES EXCEEDING 600 mm DIA REFER TO ENGINEER
2) IN WET OR SOFT GROUND SEEK GUIDANCE FROM ENGINEER
3)THE BEDDINGS MAY BE MODIFIED FOR CERTAIN SUB-SOIL CONDITIONS AT THE ENGINEERS DISCRETION
4) THE CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING ADDITIONAL PROTECTION IN AREAS SUBJECT TO LOADS FROM SITE TRAFFIC. THE CONTRACTOR SHALL IDENTIFY THESE ZONES AND RESTRICT TRAFFIC ELSEWHERE
5) SEE ALSO BS 8301
6) FOR GREATER TRENCH WIDTHS SEEK GUIDANCE FROM ENGINEER

BEDDING DETAILS LIGHT TRAFFIC AREAS

CLASS B GRANULAR BED



Pipe Size	Trench Width
100 mm	0.6 m
150 mm	0.6 m
225 mm	0.7 m
300 mm	0.8 m
375 mm	1.1 m
400 mm	1.1 m
450 mm	1.2 m
500 mm	1.2 m
600 mm	1.4 m

CLASS S GRANULAR SURROUND



CONCRETE BED & SURROUND (C.B.S.)



GRANULAR MATERIAL	
PIPE SIZE	AGGREGATE
100 mm	10 mm SINGLE SIZE
150 mm	10 OR 14mm SINGLE SIZE OF 14-5 mm GRADED
150 mm-500 mm	10,14,20 SINGLE SIZE OR 20-25 mm GRADED
600 mm	10,14,20 OR 40 mm SINGLE CRUSHED ROCK OR 40-45 mm GRADED

DIMENSION Y = - IN ROCK, CONCRETE OR MIXED SOILS CONTAINING ROCK BANDS, BOULDERS, LARGE FLINTS OR STONES OR OTHER IRREGULAR HARD SPOTS THAT RESULT IN UNEVEN TRENCH BOTTOM Y=1/4 Bc OR 200 mm WHICH EVER IS THE GREATER, BUT NOT LESS THAN 50mm UNDER COLLARS

NOTES - IN SOILS THAT PERMIT AN EVEN TRENCH BOTTOM TO BE EXCAVATED Y=1/6 Bc OR 150 mm WHICH EVER IS GREATER, BUT NOT LESS THAN 50 mm UNDER COLLARS

1) FOR PIPES EXCEEDING 600 mm DIA REFER TO ENGINEER
2) IN WET OR SOFT GROUND SEEK GUIDANCE FROM ENGINEER
3)THE BEDDINGS MAY BE MODIFIED FOR CERTAIN SUB-SOIL CONDITIONS AT THE ENGINEERS DISCRETION
4) THE CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING ADDITIONAL PROTECTION IN AREAS SUBJECT TO LOADS FROM SITE TRAFFIC. THE CONTRACTOR SHALL IDENTIFY THESE ZONES AND RESTRICT TRAFFIC ELSEWHERE
5) SEE ALSO BS 8301
6) FOR GREATER TRENCH WIDTHS SEEK GUIDANCE FROM ENGINEER

BEDDING DETAILS LORRY ACCESS AREAS

GENERAL NOTES

1. The location, size, depth and identification of existing services that may be shown or referred to on this drawing have been assessed from non intrusive observations , record drawings or the like. The contractor shall safely carry out intrusive investigations, trial holes or soundings prior to commencing work to satisfy himself that it is safe to proceed and that the assessments are accurate. any discrepancies shall be notified to gta prior to works commencing.

2. Tender or billing drawings shall not be used for construction or the ordering of materials.

3. Do not scale. All dimensions and levels to be site confirmed.

4. This drawing shall be read in conjunction with all relevant architects, consultants drawings and specifications, together with H&S plan requirements.

5. Copyright : This drawing must not be copied, amended nor reproduced without the prior written agreement of gta.

6. All drawings specifications and recommendations made by gta are subject to Local Authority and other relevant Statutory Authorities approval. Any works or services made abortive due to the client proceeding prior to these approvals is considered wholly at the Clients risk. gta hold no responsibility for resulting abortive works or costs.



PLAN



ROAD GULLY



POROUS INLET/OUTLET DETAIL (MARKED DT ON LAYOUT).

FOR ALL DRAINAGE OFFERED FOR ADOPTION, REFERENCE SHOULD BE MADE TO S104 DRAINAGE DETAILS (1702 & 1703)



PIPE DIA. Dn mm	RECOMMENDED TRENCH WIDTH Bd mm
100 mm	550
150 mm	600
225 mm	700
300 mm	750

NOTE
WHEN DIMENSION `A` IS GREATER THAN 300mm GRANULAR BED SHALL APPLY. IF LESS THAN 300mm THEN CONCRETE SURROUND. THIS DETAIL IS FOR PIPES LAID IN DRY UNIFORM SOILS ONLY. FOR WET SOILS ADD 75mm THICK LAYERS OF WEAK MIX CONCRETE UNDER BED.

GRANULAR BED

(`A` IS GREATER THAN 300mm)



CONCRETE SURROUND

(`A` IS LESS THAN 300mm)

BEDDING DETAILS FOR PIPE UNDERBUILDING



DRAIN POINT TERMINATION

NOTE:
ALL MANHOLES/CHAMBERS WITHIN BLOCK PAVED AREAS TO BE FITTED WITH SQUARE RECESSED COVER WITH MATERIAL TO MATCH SURROUND.



INSPECTION CHAMBER LOCATED CAR PARK AREAS



NOTE! ANY 450mm INSPECTION CHAMBER WITH A DEPTH EXCEEDING 1.2m THE INSPECTION CHAMBER MUST REDUCE TO 350mm dia AT THE 1.2m DEPTH TO THE COVER LEVEL. AS DETAIL ABOVE.

450mm INSPECTION CHAMBER (SIC)

NOTE:
ALL MANHOLES/CHAMBERS WITHIN BLOCK PAVED AREAS TO BE FITTED WITH SQUARE RECESSED COVER WITH MATERIAL TO MATCH SURROUND.





SHALLOW ACCESS CHAMBER (SAC)

Rev	Amendments	Date	Dsn	Chk
A1	AS BUILT ISSUE	20.03.25	MB	MR

Status: AS BUILT

Client: Gravity

Architect: AHMM

Project: LAND AT FORMER EASTBROOK PRIMARY SCHOOL

Title: Drainage Details Sheet 1 of 4

Date: February 2022 | Scale @ A1: NTS

Clients Ref. | Project Ref.: 11650

gta Civils & Transport
Maple House, 192-198 London Road,
Burgess Hill, West Sussex, RH15 9RD
Tel.01444 871444 Web: www.gtacivils.co.uk

Drawing Number: 11650-1701 | Rev.: A1



GENERAL NOTES

1. The location, size, depth and identification of existing services that may be shown or referred to on this drawing have been assessed from non intrusive observations , record drawings or the like. The contractor shall safely carry out intrusive investigations, trial holes or soundings prior to commencing work to satisfy himself that it is safe to proceed and that the assessments are accurate. any discrepancies shall be notified to gta prior to works commencing.

2. Tender or billing drawings shall not be used for construction or the ordering of materials.

3. Do not scale. All dimensions and levels to be site confirmed.

4. This drawing shall be read in conjunction with all relevant architects, consultants drawings and specifications, together with H&S plan requirements.

5. Copyright : This drawing must not be copied, amended nor reproduced without the prior written agreement of gta.

6. All drawings specifications and recommendations made by gta are subject to Local Authority and other relevant Statutory Authorities approval. Any works or services made abortive due to the client proceeding prior to these approvals is considered wholly at the Clients risk. gta hold no responsibility for resulting abortive works or costs.





TYPICAL PRECAST CONCRETE CATCHPIT (1:20 typical)

ALL SEWERS ARE DESIGNED AND PROPOSED FOR ADOPTION AS PER DESIGN AND CONSTRUCTION GUIDANCE/SEWER SECTOR GUIDANCE (DCG/SSG)

FOR ALL LOCAL DRAINAGE NOT OFFERED FOR ADOPTION, REFERENCE SHOULD BE MADE TO PRIVATE DRAINAGE DETAILS (1701)

ALL ADOPTABLE FOUL DRAINAGE TO BE CONSTRUCTED WITH EXTRA STRENGTH CLAYWARE

NOTE:
ALL WORKS CARRIED OUT PRIOR TO WRITTEN TECHNICAL APPROVAL BY ICOSA ARE AT RISK.



TYPICAL DETAIL OF LAND DRAIN



SWALE WITH FILTER STRIP & LAND DRAIN UNDER



FOR USE WHERE COVER TO PIPE IS GREATER THAN 1.2 m

TYPICAL RODDING POINT TO DEEP DRAIN RUN

Rev	Amendments	Date	Dsn	Chk
A1	AS BUILT ISSUE	20.03.25	MB	MR

Status: AS BUILT

Client: Gravity

Architect: AHMM

Project: LAND AT FORMER EASTBROOK PRIMARY SCHOOL

Title: S104 Drainage Details Sheet 2 of 4

Date	Scale @ A1
February 2022	1:200
Clients Ref.	Project Ref. 11650

gta Civils & Transport
Maple House, 192-198 London Road,
Burgess Hill, West Sussex, RH15 9RD
Tel:01444 871444 Web: www.gtacivils.co.uk

Drawing Number	Rev.
11650-1702	A1

FIGURE B 10
TYPICAL MANHOLE DETAIL - TYPE B

Depth from cover level to soffit of pipe 1.5 m to 3.0 m
Alternative Rigid material construction with concrete surround





Not to scale

FIGURE B 5
TYPICAL MANHOLE DETAIL - TYPE A (1)

Depth from cover level to soffit of pipe 3 m to 6 m with reducing slab
Rigid material construction with concrete surround





Note: Opening to be located centrally over 900 mm shaft and offset approximately 200 mm for 1200 mm diameter shaft

Not to scale

FIGURE B 15
TYPICAL MANHOLE DETAIL - TYPE C

DEPTH FROM COVER LEVEL TO SOFFIT OF PIPE LESS THAN 1.5 M
RIGID MATERIAL CONSTRUCTION





Note: The use of precast concrete chamber units to E2.29 with 150 mm GEN3 in-situ concrete complying with E4.1 and BRE Special Digest 1 in place of brickwork construction is permitted.

Not to scale

GENERAL NOTES

1. The location, size, depth and identification of existing services that may be shown or referred to on this drawing have been assessed from non intrusive observations , record drawings or the like. The contractor shall safely carry out intrusive investigations, trial holes or soundings prior to commencing work to satisfy himself that it is safe to proceed and that the assessments are accurate. any discrepancies shall be notified to gta prior to works commencing.

2. Tender or billing drawings shall not be used for construction or the ordering of materials.

3. Do not scale. All dimensions and levels to be site confirmed.

4. This drawing shall be read in conjunction with all relevant architects, consultants drawings and specifications, together with H&S plan requirements.

5. Copyright : This drawing must not be copied, amended nor reproduced without the prior written agreement of gta.

6. All drawings specifications and recommendations made by gta are subject to Local Authority and other relevant Statutory Authorities approval. Any works or services made abortive due to the client proceeding prior to these approvals is considered wholly at the Clients risk. gta hold no responsibility for resulting abortive works or costs.



PIPE BEDDING DETAILS

FIGURE B 16
TYPICAL RAMPED DETAIL (RIGID MATERIALS)
For use in manhole types A to D

Note: Steeper gradients are preferred to the use of backdrops.
Type of backdrop to be used to be agreed with the water company.



External Ramped Backdrop

Not to scale

Figure B 13
Typical arrangement of pipe junctions within manholes



Rigid pipes built into manhole should have a flexible joint as close as feasible to the external face of the structure and the length of the next rocker pipe should be as shown.

Nominal diameter (mm)	Maximum effective length (m)
150 - 600	0.6
601 - 750	1.00
over 750	1.25

All pipes entering the bottom of the manhole to have soffits level.

FOR ALL LOCAL DRAINAGE NOT OFFERED FOR ADOPTION, REFERENCE SHOULD BE MADE TO PRIVATE DRAINAGE DETAILS (1701)

ALL ADOPTABLE FOUL DRAINAGE TO BE CONSTRUCTED WITH EXTRA STRENGTH CLAYWARE

NOTE:
ALL WORKS CARRIED OUT PRIOR TO WRITTEN TECHNICAL APPROVAL BY ADOPTING AUTHORITY ARE AT RISK.

ALL SEWERS ARE DESIGNED AND PROPOSED FOR ADOPTION AS PER DESIGN AND CONSTRUCTION GUIDANCE/SEWER SECTOR GUIDANCE (DCG/SSG)

Rev.	Amendments	Date	Dsn	Chk
A1	AS BUILT ISSUE	20.03.25	MB	MR

Status: AS BUILT

Client: Gravity

Architect: AHMM

Project: LAND AT FORMER EASTBROOK PRIMARY SCHOOL

Title: S104 Drainage Details Sheet 3 of 4

Date: February 2022 | Scale @ A1: 1:200

Clients Ref. | Project Ref.: 11650

gta Civils & Transport
Maple House, 192-198 London Road.
Burgess Hill, West Sussex, RH15 9RD
Tel.01444 871444 Web: www.gtacivils.co.uk

Drawing Number: 11650-1703 | Rev.: A1

GENERAL NOTES

1. The location, size, depth and identification of existing services that may be shown or referred to on this drawing have been assessed from non intrusive observations , record drawings or the like. The contractor shall safely carry out intrusive investigations, trial holes or soundings prior to commencing work to satisfy himself that it is safe to proceed and that the assessments are accurate. any discrepancies shall be notified to gta prior to works commencing.

2. Tender or billing drawings shall not be used for construction or the ordering of materials.

3. Do not scale. All dimensions and levels to be site confirmed.

4. This drawing shall be read in conjunction with all relevant architects, consultants drawings and specifications, together with H&S plan requirements

5. Copyright : This drawing must not be copied, amended nor reproduced without the prior written agreement of gta.

6. All drawings specifications and recommendations made by gta are subject to Local Authority and other relevant Statutory Authorities approval. Any works or services made abortive due to the client proceeding prior to these approvals is considered wholly at the Clients risk. gta hold no responsibility for resulting abortive works or costs.

Rev	Amendments	Date	Dsn	Chk
A1	AS BUILT ISSUE	20.03.25	MB	MR



350 SILT BOX
WITH GRATING - S20105
WITH RECESSED COVER - S20110



CHANNEL DRAIN DETAIL (CD)



GATIC SLOTDRAIN
150mm PAVESLOT S11310
SECTION
(SD)



BACK INLET KITCHEN GULLY
D209.6

gta Civils & Transport
Maple House, 192-198 London Road,
Burgess Hill, West Sussex, RH15 9RD
Tel.01444 871444 Web: www.gtacivils.co.uk

Client	Gravity
Architect	AHMM
Project	LAND AT FORMER EASTBROOK PRIMARY SCHOOL
Title	Drainage Details Sheet 4 of 4
Status	AS BUILT
Date	JANUARY 2023
Scale @ A3	NTS
Drawing Number	11650/1704
Rev.	A1

Appendix B

LOVELL



Surface Water Manholes

Southwick

Tuesday 18 March 2025

Prepared For Lovell

10 Items Identified



SWM6



SWM16



SWM10



SWM9



SWM14



SWM12



SWM5



SWM7



SWM13



SWM1

Dan Byng
Lovell

Appendix C

LOVELL



Drainage

southwick

Tuesday 9 January 2024

Prepared For

8 Items Identified



Picture 1



Picture 2



Picture 3
300mm of stone



Picture 4



Picture 5



Picture 6



Picture 7



Picture 8

Dan Byng
Lovell

PARCHOW
GROUNDWORKS LTD



Southwick 445 - Tank Install

Tuesday, 9 January 2024

Parchow Groundwork's Lovells



Tank Dig/Shingle to Base



Dig And Stone Up
300mm thick Granular base



Installation of Crates
Crates height = 1125mm



Backfilling After Installation of the tank



SDS Ltd Sign Off QA Sheet

Checked Levels - Bottom of the Tank





Position	Eastings	Northing	Level
Dig Level 1	524783.753	105526.162	12.175
Dig Level 2	524783.368	105522.126	12.178
Dig Level 3	524783.257	105517.223	12.176
Dig Level 4	524790.114	105517.417	12.189
Dig Level 5	524797.759	105516.600	12.179
Dig Level 6	524807.708	105516.124	12.178
Dig Level 7	524807.807	105519.993	12.173
Dig Level 8	524807.795	105524.925	12.177
Dig Level 9	524799.658	105524.941	12.183
Dig Level 10	524790.544	105525.348	12.183
Dig Level 11	524793.564	105520.954	12.18

Checked Levels - Top of the Granular Base





Position	Eastings	Northing	Level
Top Stone 1	524783.751	105526.160	11.876
Top Stone 2	524783.363	105522.121	11.872
Top Stone 3	524783.254	105517.226	11.874
Top Stone 4	524790.111	105517.414	11.879
Top Stone 5	524797.756	105516.603	11.877
Top Stone 6	524807.705	105516.129	11.877
Top Stone 7	524807.809	105519.990	11.873
Top Stone 8	524807.792	105524.927	11.875
Top Stone 9	524799.655	105524.944	11.881
Top Stone 10	524790.541	105525.345	11.881
Top Stone 11	524793.562	105520.958	11.883

Design Level = 11.875m

Checked Levels - Top of the Crates





Position	Easting	Northing	Level
P1	524816.346	105523.563	12.999
P2	524815.852	105515.580	13.016
P3	524805.171	105516.414	13.001
P4	524803.711	105524.410	12.999
P5	524783.877	105525.661	12.997
P6	524783.526	105517.771	12.976

Indunil Dissanayaka
Parchow Groundworks Ltd

Appendix D

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Project-Information

Project Name:	Contract Number:	Contact:	Date:
445		**Parchow Groundworks**	**17/02/25**

Client:	**Parchow Groundworks**
Contact:	
Position:	
Road:	**Widley Farm, New Down Lane**
Town:	**Purbrook**
Post Code:	**PO7 5SE**
County:	**Hampshire**
Telephone:	

Contractor:	**All Hours Plumbing Ltd**
Contact:	**Steve Guest**
Position:	**Owner**
Road:	**70 Widley Road, Stamshaw**
Town:	**Portsmouth**
County:	**Hampshire**
Telephone:	**02392693923**
Fax:	**02392639355**
E-Mail:	**tracy@allhoursplumbing.uk**

Site:	**445**
Engineer:	
Position:	
Road:	
Town:	**Southwick**
County:	
Telephone:	

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	2	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 1** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.9M	LR	Line Turns Right
1.7M	LL	Line Turns Left
5.9M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	3	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 1** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
7.9M	JN	Line Drops In From The Right
10.0M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	4	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 1** End MH: **FIC 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.4M	MH	Camera Enters Manhole FIC 2

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	5	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 2** End MH: **FIC 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.4M	MH	Camera Enters Manhole FIC 3

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	6	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 2** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.0M	JN	Line Drops In From The Left
7.9M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	7	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 2** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.6M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	8	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 3** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.5M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	9	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 3** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.7M	JN	Line Drops In From The Right
8.0M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	10	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 3** End MH: **FIC 4** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.8M	MH	Camera Enters Manhole FIC 4

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	11	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 4** End MH: **FIC 5** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.5M	MH	Camera Enters Manhole FIC 5

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	12	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 4** End MH**: LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



9.0M	JN	Line Drops In From The Left
10.1M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	13	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 4** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.2M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	14	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 5** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.0M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	15	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 5** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.3M	JN	Line Drops In From The Right
10.0M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	16	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 5** End MH: **FAC 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.0M	MH	Camera Enters Manhole FAC 1

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	17	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FAC 1** End MH: **FAC 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.5M	MH	Camera Enters Manhole FAC 2

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	18	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FAC 1** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



6.8M JN Line Drops In From The Left

7.8M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	19	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FAC 1** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.5M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	20	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FAC 2** End MH: **FIC 6** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.4M	MH	Camera Enters Manhole FIC 6

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	21	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 6** End MH: **FIC 7** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.3M	MH	Camera Enters Manhole FIC 7

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	22	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 7** End MH: **FWMH 6** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.0M	MH	Camera Enters Manhole FWMH 6

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	24	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 7** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



9.0M	JN	Line Drops In From The Left
10.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	25	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 7** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	26	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 8** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
8.0M	JN	Line Drops In From The Right
9.8M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	27	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 8** End MH: **FIC 9** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.1M	MH	Camera Enters Manhole FIC 9

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	28	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 9** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.7M	JN	Line Drops In From The Right
8.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	29	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 9** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.0M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	30	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 10** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.3M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	31	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 10** End MH: **FIC 12** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
1.9M	JN	Line Drops In From Above From FIC 11
5.2M	MH	Camera Enters Manhole FIC 12



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	32	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 11** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
2.1M	JN	Line Drops In From The Left
8.7M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	33	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 11** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
8.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	34	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 11** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.5M	JN	Line Drops In From The Left
9.0M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	35	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 11** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	36	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 18** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.8M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	37	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 18** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.9M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	38	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 18** End MH: **FIC 19** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.8M	MH	Camera Enters Manhole FIC 19

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	39	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 19** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.2M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	40	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 19** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.2M	JN	Line Drops In From The Right
7.9M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	41	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 16** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.6M	JN	Line Drops In From The Left
8.8M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	42	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 16** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.8M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	43	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 16** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
2.1M	JN	Line Drops In From The Right
8.8M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	44	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 16** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.2M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	45	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 15** End MH: **FIC 14** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.6M MH Camera Enters Manhole FIC 14

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	46	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 14** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.2M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	47	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 14** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.2M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	48	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 17** End MH: **FIC 12** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.4M	JN	Line Drops In From Above From FIC 16
9.4M	JN	Line Drops In From Above From FIC 14
12.9M	JN	Line Drops In From The Left FIC 13
14.0M	MH	Camera Enters Manhole FIC 12



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	49	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 14** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.4M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	50	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 14** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	51	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 13** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.8M	JN	Line Drops In From The Right
9.0M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	52	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 13** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	53	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 13** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
2.2M	JN	Line Drops In From The Right
7.6M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	54	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 13** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.2M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	55	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 19** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	56	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 19** End MH**: LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	57	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 19** End MH: **FIC 20** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



2.0M MH Camera Enters Manhole FIC 20

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	58	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 20** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.6M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	59	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 20** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.0M	JN	Line Drops In From The Left
8.0M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	60	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 20** End MH**: MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
3.6M	MC	Pipe Changes To Clay
6.3M	LR	Line Turns Right
6.5M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	62	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 21** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.9M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	63	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 21** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



6.9M	JN	Line Drops In From The Right
7.7M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	64	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 24** End MH**: LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	65	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 24** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



7.3M JN Line Drops In From The Right

8.0M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	66	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 24** End MH**: FIC 21** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



2.4M JN Line Drops In From The Right From FIC 23
2.8M JN Line Drops In From The Right From FIC 22

6.2M MH Camera Enters Manhole FIC21

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	67	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 23** End MH**: LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.7M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	68	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 23** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	69	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 23** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.3M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	70	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 22** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.3M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	71	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 22** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	72	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 22** End MH**: LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.7M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	73	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 21** End MH: **FWMH 7** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



3.9M MC Pipe Changes To Clay

5.9M LR Line Turns Right

6.4M MH Camera Enters Manhole FWMH Y

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	74	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 25** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	75	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 25** End MH**: LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.4M	JN	Line Drops In From The Right
9.2M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	76	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 25** End MH: **FIC 26** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.9M MH Camera Enters Manhole FIC 26

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	77	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 26** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



7.2M JN Line Drops In From The Left

7.5M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	78	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 26** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	79	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 26** End MH: **FIC 27** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.3M MH Camera Enters Manhole FIC 27

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	80	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 27** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	81	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 27** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.2M	JN	Line Drops In From The Right
7.6M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	82	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 27** End MH: **FIC 28** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.6M MH Camera Enters Manhole FIC 28

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	83	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 28** End MH: **FIC 29** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



3.4M MH Camera Enters Manhole FIC 29

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	84	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 28** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.5M	JN	Line Drops In From The Left
10.5M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	85	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 28** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.6M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	86	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 33** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



7.8M JN Line Drops In From The Left

9.9M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	87	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 33** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	88	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 33** End MH: **FIC 32** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



3.6M MH Camera Enters Manhole FIC 32

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	89	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 32** End MH: **FIC 31** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.5M MH Camera Enters Manhole FIC 31

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	90	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 32** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.2M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	91	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 32** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



6.8M JN Line Drops In From The Right

8.0M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	92	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 31** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.2M	JN	Line Drops In From The Right
7.5M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	93	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 31** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	94	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 31** End MH: **FIC 29** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.7M MH Camera Enters Manhole FIC 29

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	95	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 30** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	96	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 30** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



7.7M JN Line Drops In From The Right

9.0M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	97	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 30** End MH: **FIC 29** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.4M MH Camera Enters Manhole FIC 29

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	98	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 29** End MH: **FWMH 5** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



6.5M MH Camera Enters Manhole FWMH 5

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	99	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 34** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.4M JN Line Drops In From The Right

8.0M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	100	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 34** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	101	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 35** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	102	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 35** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.1M	LD	Line Drops Down



5.3M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	103	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 35** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	104	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 35** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.8M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	105	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 36** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	106	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 36** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.1M	LD	Line Drops Down



5.5M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	107	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 36** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	108	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 37** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	109	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 37** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.2M	JN	Line Drops In From The Left
8.5M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	110	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 37** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.6M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	111	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 38** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.9M	JN	Line Drops In From The Left
4.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	112	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 38** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.2M	JN	Line Drops In From The Left
10.4M	LU	Line Turns Up And Is Capped Off

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	113	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 38** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	114	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 38** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.2M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	115	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 36** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.7M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	116	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 35** End MH**: FIC 39** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position Code Observation



0.0M ST Start Of Survey
0.0M WL Water Level 0 %
1.1M LL Line Turns Left
2.4M JN L;ine Drops In From The Left From FIC 35
3.6M JN Line Drops In From The Left From FIC 36
6.4M JN Line Drops In From The Left From FIC 37
14.7M JN Line Drops In From The Left From FIC 38
19.6M MH Camera Enters Manhole FIC 39

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	117	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 40** End MH: **FIC 39** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



5.8M MH Camera Enters Manhole FIC 39

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	118	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 40** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.8M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	119	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 40** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



6.8M JN L;ine Drops In From The Right

9.8M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	120	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 40** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.4M	JN	Line Drops In From The Right
5.0M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	121	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 39** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.8M	MC	Pipe Changes To Clay
6.7M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	123	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 41** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



5.5M JN Line Drops In From The Left

9.3M LU Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	124	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 41** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.5M	JN	Line Drops In From The Left
9.3M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	125	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 41** End MH: **FIC 42** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.7M	MH	Camera Enters Manhole FIC 42

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	126	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 44** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.5M	JN	Line Drops In From The Left
8.8M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	127	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 44** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.9M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	128	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 44** End MH: **FIC 43** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.7M MH Camera Enters Manhole FIC 43

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	129	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 43** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.7M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	130	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 43** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.8M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	131	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 43** End MH: **FIC 42** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



0.2M MH Camera Enters Manhole FIC 42

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	132	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 42** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	133	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place**: Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH**: FIC 42** End MH**: LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining**:	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
17/02/25		**Dry**	**Mick**	134	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 42** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.4M	MC	Pipe Changes To Clay
7.8M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	135	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **FIC 44** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**FOUL**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.0M	JN	Line Drops In From The Left
8.0M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	137	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 1** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	138	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 2** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
5.1M	JN	Line Drops In From The Right
5.7M	JN	Line Drops In From The Right
6.7M	LR	Line Turns Right
9.4M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	139	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 2** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
4.8M	JN	Line Drops In From The Left
8.4M	JN	Line Drops In From The Right
9.3M	JN	Line Drops In From The Left
10.1M	LU	Line Turns Up To Rodding Eye



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	140	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 2** End MH: **SIC 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.2M MH Camera Enters Manhole SIC 3

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	141	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 3** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.2M CR Camera Stops At Crate System

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	142	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 4** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



0.4M	CR	Camera Stops At Crate System

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	143	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 4** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



11.4M JN Line Drops In From The Left

12.0M JN Line Drops In From The Right

12.4M JN Line Drops In From The Left

12.9M JN Line Drops In From The Right

13.2M LU Camera Stops At Rodding Eye

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	144	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 4** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.2M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	145	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 4** End MH: **LAT 4** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.0M CR Camera Stops At Crate System

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	146	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 4** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
1.5M	MC	Pipe Changes To Clay
4.7M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	148	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 5** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.6M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	149	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 5** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	150	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 5** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
10.2M	JN	Line Drops In From The Right
11.6M	JN	Line Drops In From The Left
12.4M	LU	Line Turns Up To Rodding Eye

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	151	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 5** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.5M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	152	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 6** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
0.8M	CR	Camera Stops At Crate System

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	153	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 6** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
10.5M	JN	Line Drops In From The Right
10.8M	JN	Line Drops In From The Left
12.0M	JN	Line Drops In From The Left
12.1M	JN	Line Drops In From The Right
12.6M	LU	Line Turns Up To Rodding Eye

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	154	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 6** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
1.5M	JN	Line Drops In From The Left
8.0M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	155	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 6** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.7M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	157	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 7** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
8.2M	JN	Line Drops In From The Left
8.8M	JN	Line Drops In From The Left
9.3M	JN	Line Drops In From The Left
9.5M	LU	Line Turns Up To Rodding Eye

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	158	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 7** End MH: **SIC 8** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.1M MH Camera Enters Manhole SIC 8

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	159	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 8** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.2M	CR	Camera Stops At Crate System

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	160	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SAC 9** End MH: **SIC 9** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.2M	JN	Line Drops In From The Right
0.5M	JN	Line Drops In From The Left
3.8M	MH	Camera Enters SIC 9



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	161	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 9** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



9.2M	JN	Line Drops In From The Right
10.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	162	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 10** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	163	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 10** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



9.2M	JN	Line Drops In From The Left
9.7M	LU	Line Turns Up To Rodding Eye

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	164	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 11** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
7.9M	JN	Line Drops In From The Right
9.0M	JN	Line Drops In From The Right
9.6M	LU	Line Turns Up To Rodding Eye

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	165	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 11** End MH: **SIC 12** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.6M	MH	Camera Enters Manhole SIC 12

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	166	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 12** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
1.8M	LL	Line Turns Left
4.4M	LD	Line Drops Into Main



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	167	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 12** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.6M	CR	Camera Stops At Crate System

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	168	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 12** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.2M	CR	Camera Stops At Crate System

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	169	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 13** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
8.0M	JN	Line Drops In From The Left
10.0M	JN	Line Drops In From The Right
11.0M	JN	Line Drops In From The Right
11.8M	LU	LineTurns Up To Rodding Eye



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	170	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 13** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.9M	LD	Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	171`	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 14** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.0M	LR	Line Turns Right
6.5M	LU	LineTurns Up

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	172	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 14** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
0.6M	LD	Liner Drops Down
1.2M	CR	Camera Stops Crates System



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	173	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 14** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	175	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 15** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
1.4M	JN	Line Drops In From The Right
1.6M	JN	Line Drops In From The Left
4.0M	LR	Line Turns Right
7.3M	LU	Line Turns Up



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	176	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 16** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
8.1M	JN	Line Drops In From The Right
10.5M	JN	Line Drops In From The Left
11.4M	JN	Line Drops In From The Left
11.8M	LU	Line Turns Up To Rodding Eye



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	177	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 16** End MH: **SIC 17** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



4.3M	MH	Camera Enters Manhole SIC 17

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	178	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 17** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



Position	Code	Observation
2.0M	CR	Camera Stops At Crate System

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	179	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 17** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.6M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	181	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 18** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



8.9M	JN	Line Drops In Fro The Left
9.8M	JN	Line Drops In From The Left

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	183	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**NO**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 18** End MH: **SIC 19** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



2.8M MH Camera Enters Manhole SIC 19

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	184	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 21** End MH: **SIC 20** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	185	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 20** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %
9.5M	JN	Line Drops In From The Right
10.5M	JN	Line Drops In From The Right
12.8M	WL	Water Level 10 %
13.0M	JN	Line Drops In From Above



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	186	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 21** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.1M CR Camera Stops At Craste System

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	187	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 21** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	188	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 21** End MH: **LAT 3** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



2.4M JN Line Drops In From The Right

5.9M LU Line Turns Up

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	**Constructional Features**
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	189	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 21** End MH: **SMH 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



7.6M	MH	Camera Enters Manhole SMH 1

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	190	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SMH 1** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**CLAY**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



3.9M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	191	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 22** End MH: **LAT 1** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**CLAY**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



5.4M	LU	Line Turns Up

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	192	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 22** End MH: **LAT 2** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**CLAY**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



1.7M	CR	Camera Stops AAt Crate System

REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: 02392693923

Inspection Report

Date:	Job No:	Weather:	Operator:	Section Number	PLR:
18/02/25		**Dry**	**Mick**	193	
Present:	Vehicle:	Camera:	Preset:	Cleaned:	Grade:
	WM69 YNA	**Camera 1**		**Yes**	

Site; **445** Place: **Southwick**	Divsion: District: **S.W** Tape No: **1**	Start MH: **SIC 22** End MH: **MAIN** Total Length:

Purpose:	**Structural Defects**	**Size/Shape:**	**Circular dia 100mm**
Use:	**STORM**	**Material:**	**PLASTIC**
Catchment:	**P1 Schedule**	**Lining:**	
		Category:	

Position	Code	Observation
0.0M	ST	Start Of Survey
0.0M	WL	Water Level 0 %



2.9M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features






Civil Engineering - Transport Planning - Flood Risk

GTA Civils & Transport, Maple House, 192-198 London Road, Burgess Hill, West Sussex, RH15 9RD
T: 01444 871444 E: enquiries@gtacivils.co.uk www: gtacivils.co.uk
GTA Civils & Transport Limited, Registered in England No. 11917461. VAT Registration No. 319 2609 02