From: Peter Barnett
Sent: 23 November 2009 16:28
To: 'enquiries@replanning.co.uk'
Subject: ADC/0270/09 & ADC/0378/09 - 339 Brighton Road, Lancing

Dear Mr Escott

I write further to my letter dated 13 November 2009 regarding the above applications.

It has been noticed that the position of the eastern access on the swept path diagram submitted with the Transport Statement for ADC/0270/09 is incorrect and it has been shown as being further west than is shown on the Proposed Site Plan for the access alterations proposed in ADC/0378/09. It has been pointed out that this has implications for delivery vehicles exiting from this access as they may come into contact with a lamp post which is currently located between the access and bus shelter on Brighton Road. If the access position is as shown on the plan for ADC/0378/09, any delivery vehicle could come into contact with a central traffic island to the east of the access.

I shall be grateful if, in addition to the extra information requested in my previous letter, you would clarify the correct position of the access as altered and submit amended drawings and swept path analysis accordingly.

I look forward to hearing from you.

Yours sincerely

Peter Barnett

Peter Barnett **– Principal Planning Officer** | Planning Regeneration and Wellbeing, Adur District Council
Location: Civic Centre, Ham Road, Shoreham-by-Sea, West Sussex BN43 6PR
Internal: 63233 | External: 01273 263233 | E-mail: peter.barnett@adur.gov.uk

Please think before you print this and save paper