


T1 - OWNED BY UNIT 4.
(PHOENIX SYSTEMS)

TPO - 162/2/89/L

REDUCE CANOPY
BY 30%

- TREE BRANCHES SCRAPING PAINT OFF ROOF, DAMAGING METAL PANELS
- ROOF WILL WEAR