
15 Mill Road, Lancing, West Sussex, BN15 0PT.



T1 is a large Ash in the rear garden of No.15 Mill Road, Lancing.

Tree has been previously cut back from the school on the western side of the crown, causing an imbalance bias to the north, east and southern aspects of the crown. These works are in addition to a historical crown reduction to maintain the tree at a suitable size for its location.

Crown lift to give 4m ground level clearance. Reduce western aspect by approx. 1m to leave a residual crown radius of 5m. Reduce height and remainder of the crown to leave a residual crown radius of approximately 7m and a height of approx. 12m.

The proposed works, while not completely balancing the crown, will reduce the imbalance, and maintain the tree at a suitable size for its location.