




10 No front railings to be replaced

A diagram of a building facade with a textured wall and several windows. A horizontal line points from the text '10 No front railings to be replaced' to the middle window. The building is shown in profile, with a textured wall and a series of windows. The ground is indicated by a hatched pattern at the bottom.

[illegible]

© KRONA DESIGN