

From: **Ben Virtue**

Date: Tue, 15 Apr 2025 at 16:56

Subject: AWDM/0259/25 Former EDF carpark condition 21 contamination

To: louise.prew@adur-worthing.gov.uk <louise.prew@adur-worthing.gov.uk>

Cc: Sam Osborn, Suzanne Holloway, Arunima Gupta

Good afternoon,

Having reviewed the revised remedial approach which has been presented in recent correspondence, EPS confirm the strategy to remove and replace a 600mm thickness of cover soils, within the installation of a geotextile membrane at the base of this profile as a suitability precautionary and appropriate remedial measure for areas of future soft landscaping.

The purpose of the membrane would be as a deterrent (physical barrier) for anyone working in the areas of proposed soft landscaping in future, and an example of a suitable geotextile product which could be used to support this element is 'FasTrack 609 orange woven geotextile, 1500N, 75g/m²' or equivalent.

As outlined in EPS's Phase I & II Geo-Environmental Assessment Report (Ref: UK20.5034, dated 24th August 2020), details of the imported material (including chemical certification) and photographs of the installation should be provided to the local authority as evidence of completion of the measures. EPS can also provide assistance in this process including a formal Verification Report if requested.

Kind Regards,

Ben Virtue

Associate Director