
3 NORBURY


lead gulley formed here under eaves of main house around perimeter of porch
rainwater downpipe