

10th June 2026

**PHOTOGRAPHIC SCHEDULE OF WINDOWS AND DOORS @ 207 Brighton Road,
Worthing, West Sussex, BN11 2HA**

This schedule is to be read in conjunction with drawings FB26-0207 PL01B, FB26-0207 PL02N, FB26-0207 PL03B & FB26-0207 PL05.



Ground floor L to R: D1, 2no. W1. Door to be replaced, windows to be overhauled.

First floor: 3no. D4 – inaccessible from balcony at the time of survey due to being too warped to open. Windows to be overhauled.

Second floor: 2no. W9 – inaccessible due to height. Windows to be overhauled.



2no. W1 – to be overhauled.



Ground floor W2 – to be overhauled



Ground floor 3no. W4 – to be replaced



Ground floor 3no. W4 – to be replaced.

First floor: W8 – inaccessible due to height. To be overhauled.

Second floor: 2no. W12 – inaccessible due to height. Windows to be overhauled.




First floor: W8 – inaccessible due to height. To be overhauled.

Second floor: 2no. W12 – inaccessible due to height. Windows to be overhauled.



Ground floor D2 & W3 adjacent – both to be overhauled. Non original.




Ground floor W3 – to be overhauled. First floor L to R: W5, W6, W7 – to be overhauled. Non original.



First floor W5 bottom – view obscured.
To be overhauled.



First floor W5 top – view obscured.
Second floor W10 – to be overhauled.



Second floor W11 – to be replaced.