Site Images – 11 Firsdown Road



Post build images of cabin with the placement of hedging plants to the south border, with expectation to grow to at least the height of the pre-existing fence, already increased in height by 2 ft by one of the southerly neighbours





Image of cabin from the 1st floor bedroom of the house and pre-existing deck to the south of the property. Demonstrating the current view over the neighbour most southerly of the cabin due to the nature of the slope of Salvington Hill







Images of south facing window of the cabin and the addition of opaque film and blind from an internal and external propective



Image looking out of the most southerly window of the cabin if open



Image looking in the same direction but stood on the grass outside the cabin









Further images looking out from the most southerly windows of the cabin







Images looking out from the northerly windows of the cabin



Wood protection in Mendip Mist applied to the cabin







Partial and completed painted images of the cabin







Current status of the cabin at time of application, with guttering and water butt applied to the front elevation and the addition of hedging plants to the southerly border of the property



Further view of the current status of the cabin showing the full length of hedging plants installed and their comparison to the existing hedge sited next to the 2 pine trees (covered by TPO) and detailed on the site/block plan as within falling distance of the cabin